



MOTOROLA

Chip Errata
DSP56301 Digital Signal Processor
 Mask: 0F92R

Silicon Errata

Errata Number	Errata Description	Applies to Mask
ES1	<p>Description (added before 2/18/1996):</p> <p>A Conditional Change-of-Flow instruction (Jcc/Bcc) to LA does not work properly if interrupts are enabled.</p> <p>Workaround: Not available</p>	0F92R
ES2	<p>Description (added before 2/18/1996):</p> <p>The chip cannot work with a low frequency crystal (less than 500 KHz) connected as its clock source between EXTAL and XTAL pins.</p> <p>Workaround: Not available</p>	0F92R
ES3	<p>Description (added before 2/18/1996):</p> <p>If any DMA channel is active and a second DMA channel is enabled by writing DE = 1 and TM = 011 to its control register, and the next instructions cause “transfer stall” (see Appendix B-3.4.2 in the DSP56300 core specification) or “conditional transfer interlock” (see paragraph B-3.5.1 in the DSP56300 core specification), then the second DMA channel does not start data transfer.</p> <p>Workaround: Insert one NOP instruction between the DMA control register write and the sequence causing the “transfer stall” or “conditional transfer interlock”. Do not place a write instruction to the DMA control register with DE = 1 and TM = 011 as a second word of a fast interrupt routine.</p>	0F92R
ES4	<p>Description (added before 2/18/1996):</p> <p>Two sequential 1-cycle writes to the same peripheral do not work properly.</p> <p>Workaround: Not available</p>	0F92R

Freescale Semiconductor, Inc.



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Errata Number	Errata Description	Applies to Mask
ES5	<p>Description (added before 2/18/1996):</p> <p>When external bus activity is disabled (OMR[4] is set) and there is a contention between the DMA and core access to internal memory (access to the same 256-word bank), the DMA does not function properly.</p> <p>Workaround: Do not disable external bus activity (do not set OMR[4]) if the DMA will be used.</p>	0F92R
ES6	<p>Description (added before 2/18/1996):</p> <p>When the stack extension is enabled and a nested DO loop with consecutive LAs ends causing SP to return to 0, a stack extension operation which fills the HW stack is wrongly executed (but no stack error occurs), causing EP to be decremented under its lowest permitted value. If this section of the memory belongs to another program task, damage will be caused because of a stack extension operation that will overwrite these two memory locations (EP-1 and EP-2).</p> <p>Workaround: Any of the following alternatives can be used:</p> <ol style="list-style-type: none"> Guarantee that EP-1 and EP-2 memory locations are not used by any task. Separate the two consecutive LAs by one instruction. Push a dummy value onto the stack before the nested DO loop. 	0F92R
ES7	<p>Description (added before 2/18/1996):</p> <p>The STOP instruction does not work properly.</p> <p>Workaround: Not available</p>	0F92R
ES8	<p>Description (added before 2/18/1996):</p> <p>The \overline{IRQA}, \overline{IRQB}, \overline{IRQC}, \overline{IRQD}, $\overline{PINIT/NMI}$, \overline{HCLK} and \overline{RESET} pins do not have the proper 5 volt protection.</p> <p>Workaround: Not required. The pins function correctly as specified. There is no significant reliability degradation expected. It is recommended that the system apply only 3.3 volt levels to these pins, if possible.</p>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	<u>Errata Description</u>	Applies to Mask
ES9	<p>1. Description (added before 2/18/1996):</p> <p>When the HI32 is in UB mode and pulse mode of $\overline{\text{HIRQ}}$ pin is set, and TREQ and RREQ control bits in HCTR are changed simultaneously from transmit request enable to receive request enable (or vice versa), the false assertion of $\overline{\text{HIRQ}}$ pin might occur.</p> <p>Note: This is not an issue if handshake mode of $\overline{\text{HIRQ}}$ pin is used.</p> <p>Workaround: Do not change TREQ and RREQ control bits in HCTR simultaneously from transmit request enable to receive request enable (or vice versa). First disable both requests and then enable one (or both) of them.</p>	0F92R
ES10	<p>Description (added before 2/18/1996):</p> <p>Stack extension mechanism does not work properly if a conditional jump or branch to subroutine is used.</p> <p>Workaround: For the proper operation, the following instructions should not appear immediately after conditional jump or branch to subroutine:</p> <p>XY Memory Data Move (A-6.76) X Memory Move (A-6.71) Y Memory Move (A-6.73) Long Memory Data Move (A-6.75) Immediate Short Data Move (A-6.68) Register to Register Data Move (A-6.69) Address Register Update (A-6.70) X Memory and Register Data Move (A-6.72) Y Memory and Register Data Move (A-6.74) Arithmetic Instructions that allow Parallel Moves listed above IFcc and IFcc.U (A-6.41)</p> <p>Note: For this workaround, any of the listed above instructions should not be the first instruction of interrupt service routine.</p>	0F92R
ES11	<p>Description (added before 2/18/1996):</p> <p>When the DMA channel is enabled in triggered-by-request mode and the core is in the WAIT state, a false DMA data transfer might occur (e.g., one DMA request might cause two data transfers instead of one).</p> <p>Workaround: Not available</p>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Errata Number	Errata Description	Applies to Mask
ES12	<p>Description (added before 2/18/1996):</p> <p>The CILP (Interrupt Line-Interrupt Pin Configuration Register) is defined at address \$FC instead of address \$3C, as requested by the PCI specification.</p> <p>Workaround: Not available</p>	0F92R
ES13	<p>Description (added before 2/18/1996):</p> <p>If the HI32's configuration space is accessed in the PCI mode while one of the bits HAD[15:11] is set during the address phase, this access is interpreted as access to reserved area of the configuration space (i.e., write does not affect, read returns \$00000000 as data).</p> <p>Workaround: Guarantee that HAD[15:11] bits are cleared during the address phase of the configuration space access (e.g., by routing HIDESEL to any of HAD[31:16] bits, or using the corresponding PCI slot).</p>	0F92R
ES14	<p>Description (added before 2/18/1996):</p> <p>When the DMA performs external memory accesses with priority higher than the core and both continuous mode and interrupt enable bits are set in the channel's control register, then the DMA interrupt might not occur if the core performs external memory access immediately after the enabling (DE = 1) of the DMA channel.</p> <p>Workaround: In this scenario any of the following alternatives can be used:</p> <ol style="list-style-type: none">Do not set continuous mode.Use dynamic DMA-core priority.Guarantee that the core will perform at least two instructions fetched from internal memory immediately after setting of the DE.	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	Errata Description	Applies to Mask
ES15	<p>Description (added before 2/18/1996):</p> <p>While stack extension is enabled and MOVE to/from SSH is followed by Address Generation Interlock of Type0, then improper operation may occur. For example, the following sequence may generate incorrect results:</p> <pre>MOVE SSH, A MOVE #0, R7 MOVE A, X: (R7)</pre> <p>Workaround: After MOVE to/from SSH use any instruction sequence that does not cause Address Generation Interlock of Type0.</p> <p>Note: No interrupt service routine should start with Address Generation Interlock of Type0).</p>	0F92R
ES16	<p>Description (added before 2/18/1996):</p> <p>When the chip is powered up with PLL enabled (PINIT = 1), the skew between EXTAL and CLKOUT after the PLL locks cannot be guaranteed at high frequency (over 50 MHz, not 100% tested).</p> <p>Workaround: If skew between EXTAL and CLKOUT is needed, power up with PINIT = 0, and then enable the PLL by software.</p>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	Errata Description	Applies to Mask
ES17	<p>Description (added before 2/18/1996):</p> <p>A change-of-flow instruction that appears at LA-1 or LA-2 (or a two-word change-of-flow instruction at LA-3) while stack extension is enabled may cause improper operation if the preceding instruction activates the stack. For example, the following sequences may generate incorrect results:</p> <p>a. Example 1</p> <pre> DO #N, LABEL ... MOVE SSH, N3 ; stack activating instruction JSR R1 ; LA-1 NOP ; LA LABEL</pre> <p>b. Example 2</p> <pre> DO #M, LABEL1 DO #N, LABEL2 ... NOP ; stack activating instruction LABEL2 JSR R1 ; LA-1 NOP ; LA LABEL1</pre> <p>Workaround: For proper operation the following should be guaranteed:</p> <p>a. Stack activating instruction does not appear immediately before the restricted above change of flow instruction.</p> <p>Note: Any instruction at LA is a stack activating instruction, for example, in the case of nested DO-loops.)</p> <p>b. Interrupt service routine should not include more than fifteen stack pushes and pops.</p>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	<u>Errata Description</u>	<u>Applies to Mask</u>
ES18	<p>Description (added before 2/18/1996):</p> <p>If the HI32's HCVR register is read in the PCI mode and DMA transfers to DTXS are enabled, the false DMA transfers may occur.</p> <p>Workaround: Since typically the HCVR is read for HC bit polling, use HCVR write with HC = 0 instead of HC bit polling. The write can be accepted by the HI32 only if HC is cleared by the HI32 hardware; otherwise, the transaction will be retried. In the latter case, the "retry" condition indirectly signals that HC is set, whereas a successfully finished transaction means that HC is cleared by the HI32 hardware.</p>	0F92R
ES19	<p>Description (added before 2/18/1996):</p> <p>In the PCI mode, if the PCI master inserts more than one wait state when the HI32's HCVR register is read and there is data ready in HRXS, then the HRXS will be read instead of HCVR.</p> <p>Workaround: In this scenario use any of the following alternatives:</p> <ol style="list-style-type: none"> a. Use HCVR write with HC = 0 instead of HC bit polling (see workaround above). b. Read the HCVR in a non one-word transaction starting from the HI32 register with the lower PCI address (e.g., HSTR). The PCI master must not extend the HCVR read data phase (usually, zero wait states can be easily guaranteed for data phases after the first one). 	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	Errata Description	Applies to Mask
ES20	<p>Description (added 3/4/1996):</p> <p>After HC bit is set by the host processor (writing the HCVR register) in UB mode, the Host Command interrupt is executed as defined by the specification, but HC bit may remain set even after HCP status bit in DSR is cleared.</p> <p>Workaround: Host Command Interrupt Service Routine (HC_ISR) should be started with 1-cycle MOVEP instruction accessing any of the HI32's DSP-side registers (see two examples below).</p> <p>a. Example 1</p> <pre> ORG P:HC_ISR ; host command vector MOVEP A,X:M_DSR JSR <HCP_ ; BSR could be used instead of JSR HCP_ ... ; HCP ISR ... RTI </pre> <p>b. Example 2</p> <pre> ORG P:HC_ISR ; host command vector JSR >HCP_ ; BSR could be used instead of JSR HCP_ MOVEP A,X:M_DSR ; HCP ISR RTI </pre>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	Errata Description	Applies to Mask
ES21	<p>Description (added 4/16/1996):</p> <p>If the DMA channel performs non-zero wait state data accesses to/from external memory and the DMA interrupt is enabled, a false interrupt may occur in addition to the correct one.</p> <p>Workaround: Ensure that the channel's DTD status bit in the DSTR register is set before jumping to the interrupt service routine (i.e., the interrupt is correct only when DTD is set).</p> <p>Example:</p> <pre> ORG P:I_DMA2 JSSET #M_DTD2,X:M_DSTR,ISR_ ; ISR_ is interrupt service routine ; label for DMA channel 2 </pre>	0F92R
ES22	<p>Description (added 4/16/1996):</p> <p>Normally, if the PLL disabled, the PCAP pin may be connected to V_{CC}, to Ground, or be left floating. However, this device has a latchup sensitivity on the PCAP pin.</p> <p>Workaround: Do not connect the PCAP pin to Ground. If the PLL is not being used, PCAP may be connected to V_{CC} or be left floating. There is no possibility of latchup if a capacitor is the only connection to PCAP.</p>	0F92R
ES23	<p>Description (added 5/7/1996):</p> <p>When the HI32 operates in UB mode while the $\overline{\text{HIRQ}}$ pin is asserted in handshake mode (HIRH is set in the DCTR), writing zero to both the RREQ and TREQ control bits in the HCTR will not clear the interrupt request (i.e., $\overline{\text{HIRQ}}$ pin remains asserted).</p> <p>Workaround: In this scenario any of the following alternatives can be used:</p> <ol style="list-style-type: none"> Do not clear both RREQ and TREQ control bits while $\overline{\text{HIRQ}}$ pin is asserted. After both RREQ and TREQ are cleared, service the last interrupt request by the corresponding access to the HI32 host-side data registers. This causes the deassertion of $\overline{\text{HIRQ}}$ pin. 	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	<u>Errata Description</u>	<u>Applies to Mask</u>
ES24	Description (added 6/26/1996): Trace mode (TME bit is set in OSCR) does not work properly during REP instruction execution. Workaround: Host debugging software should disable tracing during REP instruction execution and enable it only after the whole REP cycle is complete. If the debugging software does not disable tracing during REP instruction execution, the user must ensure that programs do not enter the trace mode while executing a REP instruction.	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	Errata Description	Applies to Mask
ES25	<p>2. Description (added 6/26/1996):</p> <p>If the HI32 is a PCI master and receives a target disconnect (TDIS = 1 in DPSR), the Remaining Data Count (RDC[5:0] in DPSR) may be erroneous. If the disconnected burst must be completed, the new Burst Length value (BL[5:0] in DPMC) and address (AR[31:0] in DPMC and DPAR) calculation may be incorrect.</p> <p>Workaround: Reset the HI32 FIFOs (enter Mode 0) and regenerate the disconnected burst. Minimize the probability of target disconnects by selecting an appropriate Burst Length value.</p> <p>Note: Note: This issue will be fixed in the next revision of the DSP56301 in the following way:</p> <p>Note:</p> <p>a. MDT (Master Data Transferred) bit is added to the DPSR. This bit is set if all data (as defined by BL[5:0] in DPMC) is transferred in the latest completed PCI transaction and the HI32 is the PCI master. (If this bit is set, any other analysis of the DPSR status bits can be skipped).</p> <p>b. RDCQ (Remaining Data Count Qualifier) bit is added to the DPSR. If the MDT bit is cleared and the data transfer should be completed by the HI32 as a PCI master, the new burst length for the next transaction should be calculated as</p> $BL[5:0]_{\text{new}} = RDC[5:0] + RDCQ,$ <p>and the new address as</p> $AR[31:0]_{\text{new}} = AR[31:0]_{\text{old}} + BL[5:0]_{\text{old}} - BL[5:0]_{\text{new}}.$ <p>If the TAB, TRTY, or MAB status bit is set in the DPSR, the burst length and address for the next transaction should not be changed.</p>	0F92R
ES26	<p>3. Description (added 9/10/1996):</p> <p>When using the 5-V tolerant pins HP28, HP50, TXD, \overline{DE} in open drain mode, the chip clamps the voltage at the pin to about $V_{CC} + 0.4 \text{ V}$.</p> <p>Workaround: Not available.</p>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Errata Number	Errata Description	Applies to Mask
ES27	<p>4. Description (added 9/10/1996):</p> <p>If the chip is in the Debug mode and the $\overline{\text{RESET}}$ pin is asserted to bring the chip into Normal mode without asserting $\overline{\text{TRST}}$ at the same time, the chip status will continue to be read as “Debug” mode instead of the expected “User” mode, when the status is read afterwards through the JTAG port.</p> <p>Workaround: Assert the $\overline{\text{TRST}}$ pin while asserting the $\overline{\text{RESET}}$ pin.</p>	0F92R
ES28	<p>5. Description (added 9/10/1996):</p> <p>If the chip is in the Debug mode and the $\overline{\text{TRST}}$ pin is asserted, the chip status will show the chip status as “User” mode instead of the expected “Debug” mode, when the status is read afterwards through the JTAG port,.</p> <p>Workaround: Execute the following JTAG commands before reading the JTAG status:</p> <ul style="list-style-type: none"> a) Enable OnCE b) DEBUG request <p>Afterwards, the status bits will reflect the actual status of the chip and the $\overline{\text{DE}}$ pin will acknowledge “re-entering” the Debug mode.</p>	0F92R
ES30	<p>Description (added 11/18/1996):</p> <p>After the $\overline{\text{BB}}$ pin output is driven high and released, the pin output voltage level may not reach V_{CC}. The issue depends on the application board layout and the parameters of the chip process.</p> <p>Workaround: Use a restricted board layout that includes a 1 kΩ pull-up resistor connected to the $\overline{\text{BB}}$ pin with a 100 Ω resistor connected in series with, and as close as possible to, the pin. The board route from the $\overline{\text{BB}}$ pin to any component should guarantee the following parameters:</p> <ul style="list-style-type: none"> a. Route inductance < 40 nH b. Route capacitance < 15 pF c. Input capacitance < 8 pF <p>Such restrictions guarantee that when $\overline{\text{BB}}$ is driven high (deasserted), the output voltage level will be above 2.25 V at $V_{CC} = 3.3$ V.</p>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	Errata Description	Applies to Mask
ES32	<p>Description (added 2/12/1997):</p> <p>Under the PCI specification, a PCI arbiter can park the PCI bus on a specific device by asserting the \overline{GNT} signal for that device, allowing the device to have virtually instantaneous bus access (i.e. if \overline{GNT} is asserted for the device, no \overline{REQ} assertion is required to start a transaction). The device on which the bus is parked can either be a single preferred device or the last device to use the bus (the recommended choice). The PCI specification requires that when the bus is parked on a device and another device requires the bus and the arbiter deasserts the \overline{GNT} signal to remove bus parking, the device on which the bus is parked must immediately release the bus and not perform any transactions. However, in the DSP56301, if the PCI arbiter performs bus parking on the HI32, and the HI32 is configured as the PCI bus master, and the HI32 asserts the \overline{HREQ} signal at the same time that the PCI arbiter deasserts the \overline{HGNT} signal (removing the bus parking), the HI32 may hold the bus mastership for one transaction.</p> <p>Workaround:</p> <p>Do not allow the PCI bus arbiter to park the bus on the HI32.</p>	0F92R
ES33	<p>Description (added 3/3/1997):</p> <p>When using the JTAG instructions SAMPLE/PRELOAD, EXTEST, and CLAMP, erroneous data may be driven out on the parallel pins and TDO. Data cannot be shifted through the Boundary Scan Register (BSR) using the SAMPLE/PRELOAD instruction. Because the BSR must be preloaded using the SAMPLE/PRELOAD instruction, the EXTEST and CLAMP instructions cannot be used for testing the board connections.</p> <p>Workaround: None available.</p>	0F92R
ES34	<p>Description (added 3/3/1997):</p> <p>The Self-Configuration procedure of the HI32 does not work properly when executed from external memory (either program or data fetches).</p> <p>Workaround: Download program and data to the internal memory and then execute the Self-Configuration procedure from internal memory (both program and data fetches).</p>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Errata Number	<u>Errata Description</u>	Applies to Mask
ES35	<p>Description (added 4/7/1997):</p> <p>When the HI32 is a PCI master and initiates any type of write transaction after another PCI master performs Memory Write transaction to another PCI agent, the DRXR FIFO pointers of the HI32 may be corrupted.</p> <p>Workaround:</p> <p>To guarantee that 'valid' DRXR data is not lost, it should be read prior the HI32 initiates any type of the write transaction. This should be done after each write transaction of any type initiated by the HI32 under mentioned above conditions. Empty the DRXR FIFO reading both master and slave 'dummy' data according to the SRRQ and MRRQ status bits, using the core moves.</p>	0F92R
ES37	<p>Description (added 9/2/1997):</p> <p>In PCI mode, improper HI32 operation may result if the HTXR/HRXS registers are accessed by the PCI master at byte address Base_Address + (N × 2048 + 16), where N is an integer from 1-31.</p> <p>Workaround:</p> <p>Not available.</p>	0F92R
ES41	<p>6. Description (added 9/15/97):</p> <p>The HCLK pin of the HI32 presents an input capacitive load of almost 30 pF, which exceeds the permissible maximum load of 12 pF as specified in the PCI Specification Version 2.1. This may cause improper HI32 operation in PCI systems.</p> <p>Note: The effect of this extra load may vary from system to system, depending on PCI clock driver strength.</p> <p>Workaround:</p> <p>Use a zero-propagation-delay external PLL device (e.g., CY2305) to buffer the PCI clock signal. This solution does not enable spread-spectrum PCI clocking.</p>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	<u>Errata Description</u>	Applies to Mask
ES42	<p>Description (added 3/3/ 98):</p> <p>When a Direct Memory Access (DMA) channel is in Line mode (i.e., the DMA Transfer Mode is DTM = 010) with address modes defined by DMA Three Dimensional mode D3D = 0 and DMA = 10010x (i.e., the DMA Counter (DCO) is in mode A), and the DCO value is greater than \$FFF, then the DMA does not function properly. This address mode implies “no update” at the destination and “no update” or “post increment by 1” mode at the source.</p> <p>Workaround:</p> <p>Use Block Transfer mode (i.e., DTM = 000). For the DCO and DMA Address Mode (DAM) settings described in this erratum, the Line Transfer mode of DMA is identical to its Block Transfer mode, so this combination is redundant. In fact, a block containing only one line is still a block.</p>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	Errata Description	Applies to Mask
ES44	<p>Description (added 3/3/98, modified 3/11/98): Let's say that "channel A" is the DMA channel servicing the HI32, and that "channel B" is another DMA channel that has been disabled by software. Then, depending on the DMA Request Source field (DRS[4:0]) of the two channels, channel A may be stalled by channel B being disabled. Channel A may be stalled when the DMA Channel Enable (DE) bit in the DMA Control Register is cleared by software in the following cases:</p> <ul style="list-style-type: none"> • DE bit of channel B cleared by software because of <ul style="list-style-type: none"> - a Transfer Done from DMA channel 0 (DRSb = 00100) or - an ESS11 Receive Data (DRSb = 01100) or then channel A may be stalled by a Host Slave Receive Data (DRSa = 11100). • DE bit of channel B cleared by software because of <ul style="list-style-type: none"> - a Transfer Done from DMA channel 1 (DRSb = 00101) or - an ESS11 Transmit Data (DRSb = 01101) or then channel A may be stalled by a Host Master Receive Data (DRSa = 11101). • DE bit of channel B cleared by software because of <ul style="list-style-type: none"> - a Transfer Done from DMA channel 2 (DRSb = 00110) or - an SCI Receive Data (DRSb = 01110) or then channel A may be stalled by a Host Slave Transmit Data (DRSa = 11110). • DE bit of channel B cleared by software because of <ul style="list-style-type: none"> - a Transfer Done from DMA channel 3 (DRSb = 00111) or - an SCI Transmit Data (DRSb = 01111) or then channel A may be stalled by a Host Master Transmit Data (DRSa = 11111). <p>Workaround: Use either one of the following alternatives:</p> <ul style="list-style-type: none"> • Clear and set the DE bit of channel A immediately after you clear the DE bit of channel B. • Avoid a software clear of the DE bit of channel B. 	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	<u>Errata Description</u>	Applies to Mask
ES45	<p>Description (added 3/3/ 98):</p> <p>When the Host Command Vector Register (HCVR) is written in Peripheral Component Interconnect (PCI) mode while the Receive Buffer Lock Enable (RBLE) bit is set in the DSP PCI Control Register (DPCR), the Host Data Transfer Complete (HDTC) status bit in DSP PCI Status Register (DPSR) may be set falsely, thus also causing an HDTC interrupt if that interrupt has been enabled by the Transfer Complete Interrupt Enable (TCIE) bit in the DPCR.</p> <p>Workaround:</p> <p>Use either one of the following alternatives:</p> <ul style="list-style-type: none"> • Clear HDTC, if it is set, by writing it with 1 in the Host Command Interface Status Register (ISR). • Clear HDTC, if it is set, by writing it with 1; use software-dependent information to distinguish between a false and true HDTC setting. For example, you do either of the following: <ul style="list-style-type: none"> - Alter the destination address pointer if the DSP Receive Data Register (DRXR) data is being transferred by the DSP core. The pointer will be changed if the HDTC setting is true. - Alter the destination address or counter registers of the DMA channel if the DRXR data is being transferred by the DMA. The registers will be changed if the HDTC setting is true. 	0F92R
ES56	<p>Description (added before 2/18/1996):</p> <p>JTAG-related errors:</p> <p>The reset value of the JTAG Instruction Register is 1 (SAMPLE/PRELOAD), instead of 2 (ID-CODE), which is required by the standard.</p> <p>Workaround: Not available</p>	0F92R
ES57	<p>JTAG-related errors:</p> <p>The user may not read several ID devices in a daisy-chain as the chip inserts zeros after its IDR value.</p> <p>Workaround: Read the device IDRs one at a time while keeping all the other devices in BYPASS.</p>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Errata Number	Errata Description	Applies to Mask
ES58	<p>The user may not read the chip's pre-FIFO, FIFO, or OGDBR registers when in a daisy-chain configuration.</p> <p>Workaround: Read these registers while keeping all the other devices in BYPASS.</p>	0F92R
ES59	<p>JTAG-related errors:</p> <p>Description (added before 2/18/1996):</p> <p>The user may not write the OnCE™ Command Register (OCR) when in a daisy-chain configuration.</p> <p>Workaround: Write OCR register while keeping all the other devices in BYPASS.</p>	0F92R
ES60	<p>JTAG-related errors:</p> <p>The data in the \overline{BL} pin, Port A data bus D[23:0], and the HI32 pins HP[50:0] might be erroneous in EXTEST JTAG mode.</p> <p>Workaround: Do not use EXTEST for these pins.</p>	0F92R
ES61	<p>After exiting EXTEST, a false debug request might be received.</p> <p>Workaround: After exiting EXTEST, assert \overline{TRST} pin (Test Reset) before normal activity.</p>	0F92R
ES81	<p>Description (added 5/1/98):</p> <p>The HI32 may generate a wrong PAR signal.</p> <p>Workaround:</p> <p>If possible, the system should ignore parity errors generated in such a case.</p>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	Errata Description	Applies to Mask
ES84	<p>Description (added 5/13/98):</p> <p>When software disables a DMA channel (by clearing the DE bit of the DCR) , the DTD status bit of the channel may not be set if any of the following events occur:</p> <ol style="list-style-type: none"> Software disables the DMA channel just before a conditional transfer stall (Described by App B-3.5.1,UM). Software disables the DMA channel at the end of the block transfer (that is after the counter is loaded with its initial value and transfer of the last word of the block is completed). <p>As a result, the Transfer Done interrupt might not be generated.</p> <p>Workaround: Avoid using the instruction sequence causing the conditional transfer stall (See DSP56300 UM, App B-3.5.1 for description) in fast interrupt service routines. Every time the DMA channel needs to be disabled by software, the following sequence must be used :</p> <pre> bclr #DIE,x:M_DCR ; not needed if DIE is cleared bclr #DE,x:M_DCR ; instead of two instructions above, one 'movep' instruction may be used ; to clear DIE and DE bits movep #DCR_Dummy_Value,x:M_DCR bclr #DE,x:M_DCR nop nop </pre> <p>Here, the DCR_Dummy_value is any value of the DCR register that complies with the following requirements:</p> <ul style="list-style-type: none"> DE is set; DIE is set if Transfer Done interrupt request should be generated and cleared otherwise; DRS[4:0] bits must encode a reserved DMA request source (see the following list of reserved DRS values); <p>List of reserved DRS[4:0] values (per device):</p> <ul style="list-style-type: none"> DSP56302, DSP56309, DSP56303, DSP56304, DSP56362 — 10101-11111 DSP56305 — 11011 DSP56301 — 10011-11011 DSP56307 — 10111-11111 	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	<u>Errata Description</u>	Applies to Mask
ES86	<p>Description (added 4/23/98):</p> <p>If the HI32 performs a write transaction as a PCI master and the transaction is disconnected by the target, the value of the MTRQ status bit in the DPSR register may be wrong.</p> <p>Workaround:</p> <p>Do not use an MTRQ status bit-related interrupt or polling. (The related DMA functionality is not affected by this issue.)</p>	0F92R
ES87	<p>Description (added 5/28/98):</p> <p>When the HI32 is an active PCI target, it does not set the DPE bit in the CSTR register if an address parity error occurs.</p> <p>Workaround :</p> <p>The Host can get information about the Address Parity status either by reading the SSE bit (in the CSTR) or by indirectly reading the (e.g. via Host Command) the APER bit in the DPSR register.</p>	0F92R
ES89	<p>Description (added 6/25/98):</p> <p>If the SCI Receiver is programmed to work with a different serial clock than the SCI Transmitter so that either the Receiver or Transmitter is using the external serial clock and the other is using the internally-generated serial clock—RCM and TCM in the SCCR are programmed differently)—then the internal serial clock generator will not operate and the SCI portion (Receiver or Transmitter) clocked by the internal clock will be stuck.</p> <p>Workaround:</p> <p>Do not use SCI with the two SCI portions (Receiver and Transmitter) clocked by different serial clocks; use either both externally or both internally clocked.</p> <p>Or:</p> <p>When using both portions of the SCI (Receiver & Transmitter), do not program different values on RCM and TCM in the SCCR.</p>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Errata Number	<u>Errata Description</u>	Applies to Mask
ES95	<p>Description (added 8/15/98):</p> <p>If more than a single DMA channel is enabled while the DSP stays in the WAIT processing state, and triggering one of the DMA channels causes an exit from the WAIT state (See A-6.115, UM), triggering another DMA channel might cause improper DMA operation.</p> <p>Workaround:</p> <p>Assure that only a single DMA channel can be triggered during DSP WAIT state. If the application cannot guarantee this, other DMA channels should be disabled before the WAIT processing state is entered and then reenabled after WAIT state is exited.</p>	0F92R
ES101	<p>Description (added 10/26/98):</p> <p>If the reset mode is expanded mode (for example, mode 0 or mode 8 on the DSP5630x), A MOVE (not a PROGRAM FETCH) from internal P memory to any destination may not work properly.</p> <p>Workaround:</p> <p>After each reset ($\overline{\text{RESET}}$) negation and before the first move from internal program memory, execute the following sequence:</p> <pre>BSET #M_CE, sr NOP NOP NOP BCLR #M_CE, sr</pre>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	<u>Errata Description</u>	Applies to Mask
ES104	<p>Description: (added 11/24/98):</p> <p>An improper operation may occur when all the following conditions apply:</p> <ul style="list-style-type: none"> • The DMA channel is in a mode that does not automatically clear the DE bit at the end of the block (DTM[2:0] = 1xx in DCR). • This channel is disabled by software (by clearing DE in DCR) while it is triggered for a new transfer. • The previous operation is not yet completed. <p>Workaround:</p> <p>The DMA channel should be disabled only when it is not triggered for a new transfer, i.e. when the DACT bit in the DSTR register is cleared.</p> <p>Note: To perform this operation most efficiently, all other DMA channels should be disabled.</p>	0F92R
ES107	<p>Description (added 12/8/98):</p> <p>The HDTC status bit (relevant only if the RBLE control bit is set) may not be set properly when both of the following conditions apply:</p> <p>a) DSP software clears the HDTC bit while the PCI bus is parked on the HI32.</p> <p>b) The PCI master read transaction is initiated by the HI32 while the bus is still parked on the HI32.</p> <p>Workaround:</p> <p>Use one of the following alternatives:</p> <ol style="list-style-type: none"> 1. Avoid bus parking on the HI32. 2. Enter the Personal Software Reset (HM[2:0]=0) in HDTC ISR. 3. Poll the MRRQ and SRRQ status bits before the start of each master read transaction (e.g. in MARQ ISR). Start this transaction only when both MRRQ and SRRQ are cleared. The HDTC status bit should be cleared by the DSP software as defined in the specification. 	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	Errata Description	Applies to Mask
ES114	<p>Description (added 4/19/99, revised 4/30/99):</p> <p>A DMA channel may operate improperly when the address mode of this channel is defined as three-dimensional (D3D=1) and DAM[5:0] = 1xx 1 10 or DAM[5:0] = 01xx 10 (i.e., triple counter mode is E).</p> <p>Workaround:</p> <p>Use the triple counter modes C(DAM[1:0]=00) or D(DAM[1:0]=01) instead of the E(DAM[1:0]=10) mode.</p>	0F92R
ES115	<p>Description (added 4/19/99):</p> <p>When a DMA channel (called channel A) is disabled by software clearing the channel's DCR[DE] bit, the DTD bit may not get set, and the DMA end of the block interrupt may not happen if one of the following occurs:</p> <ol style="list-style-type: none"> 1. There is another channel (channel B) executing EXTERNAL accesses, and the DE bit of channel A is being cleared by software at the end of the channel B word transfer - if channel B is in Word transfer mode, or at the end of the channel B line transfer - if channel B is in Line Transfer mode, or at the end of the channel B block transfer - if channel B is in Block transfer mode. 2. This channel (A) is executing EXTERNAL accesses, and the DE bit of this channel (A) is being cleared by software at the end of the channel B word transfer - if channel B is in Word transfer mode, or at the end of the channel B line transfer - if channel B is in Line transfer mode. <p>Workaround:</p> <p>Avoid executing a DMA external access when any DMA channel should be disabled. This can be done as follows. Every time the DMA channel needs to be disabled by software, the following sequence must be used:</p> <pre> ; ; initialize an unused DMA channel "C" movep #DSR_swflag, x:M_DSRC ; ; here DSR_swflag is an ; ; unused X, Y or P memory ; ; location, should ; ; be initialized to ; ; \$800000 ; ; M_DSRC - address of the ; ; channel C DSR register. </pre>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	Errata Description	Applies to Mask
ES115 cont.	<pre> movep #DDR_swflag, x:M_DDRC ;; DDR_swflag is an unused ;; X, Y or P memory ;; location, should be ;; initialized to \$000000 ;; M_DDRC - ;; address of the channel C ;; DDR register . movep #TR_LENGTH, x:M_DCOC ;; see below the definition ;; of the TR_LENGTH value, ;; M_DCOC - address ;; of the channel C DCO register .movep #1f0240, x:M_DCRC ;; M_DCRB - address of the ;; channel C DCR register. ;; Set transfer mode - ;; block transfer, ;; triggered by ;; software highest ;; priority, continuous ;; mode on no-update ;; source and destination ;; address mode X memory ;; location for source ;; and destination (can be ;; chosen by ;; user accordingly to ;; DSR_swflag/DDR_swflag) </pre>	0F92R
ES115 cont.	<pre> ;; disable DMA channel "A" ori #3, mr ;; mask all interrupts bset #23, x:M_DCRC ;; enable DMA channel C bclr #23,x:DDR_swflag,* ;; wait until DMA channel C ;; begin transfer bclr #23, x:M_DCRA ;; disable DMA channel A nop nop jclr #M_DTDA, x:M_DSTR,* ;; polling DTD bit of the ;; DMA channel A, </pre> <p>The TR_LENGTH value can be defined as the maximum length of the external DMA transfer—from the length of the read DMA cycle and from the length of the write DMA cycle. The length of the external read/write DMA cycle can be defined as the length of the PORTA external access. The length of the internal read/write DMA cycle can be defined in the errata case as 2 DSP clock cycles. The TR_LENGTH can be found as sum of the lengths of the DMA read and DMA write cycles.</p>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	<u>Errata Description</u>	Applies to Mask
ES124	<p>Description (added 9/11/99) (reclassified from documentation to silicon errata 11/11/99):</p> <p>When an external PCI master executes a configuration space read from the HI32 with an odd number of byte lanes enabled (for example, $\overline{BE3} - \overline{BE0} = 1000$), the DSP drives the parity signal (HPAR) with the wrong value. This is because the $\overline{BE3} - \overline{BE0}$ signals are ignored (erroneously) when generating the parity value during configuration space reads.</p> <p>Workaround: None.</p> <p>Pertains to: The HI32 (PCI) chapter of the user's manual, in the section on PCI Mode (DCTR[HM]=\$1). In Revision 2 of the <i>DSP56301 User's Manual</i>, this section is 6.5.2 on page 6-14. The information should accompany the bullet on Memory-Space and configuration transactions as a target.</p> <p>NOTE: Was documentation errata, ED39.</p>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Documentation Errata

Errata Number	<u>Errata Description</u>	<u>Applies to Mask</u>
ED1	<p>Description (revised 11/9/98):</p> <p>XY memory data move does not work properly if the X-memory move destination is internal I/O and the Y-memory move source is a register used as destination in the previous adjacent move from non Y-memory OR the Y-memory move destination is a register used as source in the next adjacent move to non Y-memory.</p> <p>Here are examples of the two cases (where x:(r1) is a peripheral):</p> <p>Example 1:</p> <pre>move #\$12,y0 move x0,x:(r7) y0,y:(r3) (while x:(r7) is a peripheral).</pre> <p>Example 2:</p> <pre>mac x1,y0,a x1,x:(r1)+ y:(r6)+,y0 move y0,y1</pre> <p>This is not a bug, but a documentation update. Any of the following alternatives can be used:</p> <ol style="list-style-type: none"> Separate these two consecutive moves by any other instruction. Split XY Data Move to two moves. 	0F92R
ED2	<p>Description (added before 2/18/1996):</p> <p>\overline{BL} pin timings T198 and T199 in the Data Sheet are changed, improving the arbitration latency: T198 is 5 ns (max), T199 is 0 ns (min).</p> <p>This is not a bug, but a documentation update.</p>	0F92R
ED3	<p>Description (added 5/7/1996):</p> <p>A one-word conditional branch instruction at LA-1 is not allowed.</p> <p>This is not a bug, but a documentation update.</p>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	Errata Description	Applies to Mask
ED4	<p>Description (added 11/11/1996):</p> <p>The following instructions should not start at address LA:</p> <p>MOVE to/from Program space {MOVEM, MOVEP (only the P space options)}</p> <p>This is not a bug but a documentation update (Appendix B, DSP56300 Family Manual).</p>	0F92R
ED6	<p>Description (added 4/9/98)</p> <p>When the $\overline{\text{HIRQ}}$ pin is used in pulse mode (HIRH=0 in DCTR), the LT[7:0] value (in CLAT) should not be zero. This is not a bug but a documenta</p>	0F92R
ED7	<p>Description (added 1/27/98):</p> <p>When activity passes from one DMA channel to another and the DMA interface accesses external memory (which requires one or more wait states), the DACT and DCH status bits in the DMA Status Register (DSTR) may indicate improper activity status for DMA Channel 0 (DACT = 1 and DCH[2:0] = 000).</p> <p>Workaround:</p> <p>None.</p> <p>Pertains to: DSP56300 Family Manual, Sections 8.1.6.3 and 8.1.6.4</p>	0F92R
ED8	<p>Description (added 7/7/1997):</p> <p>The timing for HSAK is no longer qualified by the data strobe. The new timing numbers are:</p> <ol style="list-style-type: none"> T318—HSAK assertion from HA0–HA10 and HAEN valid is 30.0 ns maximum. T319—HSAK assertion hold from HA0-HA10 and NAEN not valid is 2.0 ns minimum. <p>Pertains to: Data Sheet, Table on Universal Bus Mode Timing Parameters, Table 2-19 (Page 2-61 for 301 and Page 2-49 for 305)</p>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	Errata Description	Applies to Mask															
ED9	<p>Description (added 1/27/98):</p> <p>When the SCI is configured in Synchronous mode, internal clock, and all the SCI pins are enabled simultaneously, an extra pulse of 1 DSP clock length is provided on the SCLK pin.</p> <p>Workaround:</p> <ol style="list-style-type: none"> a. Enable an SCI pin other than SCLK. b. In the next instruction, enable the remaining SCI pins, including the SCLK pin. <p>Pertains to: UM, SCI Chapter (Use the 302 UM as your reference, Section 8.4.2, "SCI Initialization")</p>	0F92R															
ED10	<p>Description (added 5/13/98):</p> <p>The HI32 may operate improperly in PCI mode when the TWSD bit is set in the HCTR register.</p> <p>Workaround:</p> <p>Do not set the TWSD bit in the HCTR register; this bit is reserved. This is a documentation change.</p>	0F92R															
ED12	<p>Description (added 5/13/98):</p> <p>When the HI32 is in PCI mode, the HTF control bits affect the address insertion (the IAE bit is set in the DPCR register) in the same way they affect the transferred data.</p> <p>Address as appears on the PCI bus: \$12345678</p> <table border="0" data-bbox="396 1465 1177 1669"> <thead> <tr> <th data-bbox="396 1465 521 1499">HTF[1:0]</th> <th colspan="2" data-bbox="906 1465 1154 1499">Inserted Address</th> </tr> </thead> <tbody> <tr> <td data-bbox="396 1524 428 1558">00</td> <td data-bbox="906 1524 1024 1558">\$005678,</td> <td data-bbox="1062 1524 1177 1558">\$001234</td> </tr> <tr> <td data-bbox="396 1562 428 1596">01</td> <td colspan="2" data-bbox="906 1562 1016 1596">\$345678</td> </tr> <tr> <td data-bbox="396 1600 428 1633">10</td> <td colspan="2" data-bbox="906 1600 1016 1633">\$345678</td> </tr> <tr> <td data-bbox="396 1638 428 1671">11</td> <td colspan="2" data-bbox="906 1638 1016 1671">\$123456</td> </tr> </tbody> </table> <p>Workaround:</p> <p>This is a documentation update.</p>	HTF[1:0]	Inserted Address		00	\$005678,	\$001234	01	\$345678		10	\$345678		11	\$123456		0F92R
HTF[1:0]	Inserted Address																
00	\$005678,	\$001234															
01	\$345678																
10	\$345678																
11	\$123456																



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	Errata Description	Applies to Mask
ED13	<p>Description (added 5/15/98):</p> <p>When the HI32 is in PCI mode, the Insert Address Enable control bit (IAE=1) can be set only with the Receive Buffer Lock Enable control bit set (RBLE=1 in the DPCR register.)</p>	0F92R
ED15	<p>Description (added 7/21/98):</p> <p>The DRAM Control Register (DCR) should not be changed while refresh is enabled. If refresh is enabled only a write operation that disables refresh is allowed.</p> <p>Workaround:</p> <p>First disable refresh by clearing the BREN bit, than change other bits in the DCR register, and finally enable refresh by setting the BREN bit.</p>	0F92R
ED17	<p>Description (added 9/28/98):</p> <p>In all DSP563xx technical datasheets, a note is to be added under "AC Electrical Characteristics" that although the minimum value for "Frequency of Extal" is 0MHz, the device AC test conditions are 15MHz and rated speed.</p> <p>Workaround:</p> <p>N/A</p>	0F92R
ED18	<p>Description (added 11/2/98):</p> <p>The PCI host must not change the values of the HBE[3:0] bits during PCI read transactions from the HI32 as a PCI target.</p>	0F92R
ED19	<p>Description (added 11/9/98):</p> <p>To guarantee the proper HI32 operation, the DMA should service the HI32 under the following restrictions:</p> <ul style="list-style-type: none"> • Two DMA channels should not service the DRXR FIFO if master and slave data is mixed there. • The DMA data transfers should not be concurrent with the 56300 Core data transfers to/from the same HI32 data FIFO. 	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	Errata Description	Applies to Mask
ED20	Description (added 11/24/98): In the Technical Datasheet Voh-TTL should be listed at 2.4 Volts, not as: $TTL = V_{CC} - 0.4$ Workaround: This is a documentation update.	0F92R
ED21	Description (added 11/24/98): In the Technical Datasheet Iol should be listed as 1.6 mA, not as 3.0 mA. Workaround: This is a documentation update.	0F92R
ED24	Description (added 11/24/98): The technical datasheet supplies a maximum value for internal supply current in Normal, Wait, and Stop modes. These values will be removed because we will specify only a "Typical" current. Workaround: This is a documentation update.	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	<u>Errata Description</u>	<u>Applies to Mask</u>
ED25	<p>Description (added 12/16/98):</p> <p>Current definition:</p> <p>HDTC is set if SRRQ and MRRQ are cleared (i.e. the host-to-DSP data path is emptied by DSP56300 core reads) under one of the following conditions:</p> <ul style="list-style-type: none"> • a non-exclusive PCI write transaction to the HTXR terminates or <u>completes</u> • <u>HLOCK</u> is negated after the completion of an exclusive write access to the HTXR • the HI32 initiates a read transaction. The HI32 disconnects (retry or disconnect-C) forthcoming write accesses to the HTXR as long as HDTC is set. <p>New definition:</p> <p>HDTC is set if SRRQ and MRRQ are cleared (i.e. the host-to-DSP data path is emptied by DSP56300 Core reads) under one of the following conditions:</p> <ul style="list-style-type: none"> • a non-exclusive PCI write transaction to the HTXR terminates or <u>completes</u> • <u>HLOCK</u> is negated after the completion of an exclusive write access to the HTXR. The HI32 disconnects (retry or disconnect-C) forthcoming write accesses to the HTXR as long as HDTC is set. <p>Note: The HDTC bit is not set after a read transaction initiated by the HI32 as a PCI master.</p> <p>Workaround:</p> <p>NTR</p>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	<u>Errata Description</u>	<u>Applies to Mask</u>
ED26	<p>Description (added 1/6/99):</p> <p>The specification DMA Chapter is wrong.</p> <p>“Due to the DSP56300 Core pipeline, after DE bit in DCRx is set, the corresponding DTDx bit in DSTR will be cleared only after two instruction cycles.”</p> <p>Should be replaced with:</p> <p>“Due to the DSP56300 Core pipeline, after DE bit in DCRx is set, the corresponding DTDx bit in DSTR will be cleared only after three instruction cycles.”</p>	0F92R
ED28	<p>Description (added 1/7/1997; identified as Documentation Errata 2/1/99):</p> <p>When two consecutive LAs have a conditional branch instruction at LA-1 of the internal loop, the part does not operate properly. For example, the following sequence may generate incorrect results:</p> <pre> DO #5, LABEL1 NOP DO #4, LABEL2 NOP MOVE (R0) + BSCC _DEST ; conditional branch at LA-1 of internal loop NOP ; internal LA LABEL2 NOP ; external LA LABEL1 NOP NOP _DEST NOP NOP RTS </pre> <p>Workaround: Put an additional NOP between LABEL2 and LABEL1.</p> <p>Pertains to: DSP56300 Family Manual, Appendix B, Section B-4.1.3, “At LA-1.”</p>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	Errata Description	Applies to Mask
ED29	<p>Description (added 9/12/1997; identified as a Documentation errata 2/1/99):</p> <p>When the ESSI transmits data with the CRA Word Length Control bits (WL[2:0]) = 100, the ESSI is designed to duplicate the last bit of the 24-bit transmission eight times to fill the 32-bit shifter. Instead, after shifting the 24-bit word correctly, eight 0s are being shifted.</p> <p>Workaround:</p> <p>None at this time.</p> <p>Pertains to: UM, Section 7.4.1.7, "CRA Word Length Control." The table number is 7-2.</p>	0F92R
ED30	<p>Description (added 9/12/1997; identified as a Documentation errata 2/1/99):</p> <p>When the ESSI transmits data in the On-Demand mode (i.e., MOD = 1 in CRB and DC[4:0] = \$00000 in CRA) with WL[2:0] = 100, the transmission does not work properly.</p> <p>Workaround:</p> <p>To ensure correct operation, do not use the On-Demand mode with the WL[2:0] = 100 32-bit Word-Length mode.</p> <p>Pertains to: UM, Section 7.5.4.1, "Normal/On-Demand Mode Selection."</p>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	<u>Errata Description</u>	<u>Applies to Mask</u>
ED31	<p>Description (added 9/12/1997; modified 9/15/1997; identified as a Documentation errata 2/1/99):</p> <p>Programming the ESSI to use an internal frame sync (i.e., SCD2 = 1 in CRB) causes the SC2 and SC1 signals to be programmed as outputs. If however, the corresponding multiplexed pins are programmed by the Port Control Register (PCR) to be GPIOs, then the GPIO Port Direction Register (PRR) chooses their direction, but this causes the ESSI to use an external frame sync if GPIO is selected.</p> <p>Note: This errata and workaround apply to both ESSI0 and ESSI1.</p> <p>Workaround:</p> <p>To assure correct operation, either program the GPIO pins as outputs or configure the pins in the PCR as ESSI signals.</p> <p>Note: The default selection for these signals after reset is GPIO.</p> <p>Pertains to: UM, Section 7.4.2.4, "CRB Serial Control Direction 2 (SCD2) Bit 4"</p>	0F92R
ED32	<p>Description (added 11/9/98; identified as a Documentation errata 2/1/99):</p> <p>When returning from a long interrupt (by RTI instruction), and the first instruction after the RTI is a move to a DALU register (A, B, X, Y), the move may not be correct, if the 16-bit arithmetic mode bit (bit 17 of SR) is changed due to the restoring of SR after RTI.</p> <p>Workaround:</p> <p>Replace the RTI with the following sequence:</p> <pre> movec ssl, sr nop rti </pre> <p>Pertains to: DSP56300 Family Manual. Add a new section to Appendix B that is entitled "Sixteen-Bit Compatibility Mode Restrictions."</p>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	<u>Errata Description</u>	<u>Applies to Mask</u>
ED33	<p>Description (added 12/16/98; identified as a Documentation errata 2/1/99):</p> <p>When Stack Extension mode is enabled, a use of the instructions BRKcc or ENDDO inside do loops might cause an improper operation.</p> <p>If the loop is non nested and has no nested loop inside it, the errata is relevant only if LA or LC values are being used outside the loop.</p> <p>Workaround:</p> <p>If Stack Extension is used, emulate the BRKcc or ENDDO as in the following examples. We split between two cases, finite loops and do forever loops.</p> <p>1) Finite DO loops (i.e. not DO FOREVER loops)</p> <p>=====</p> <p>BRKcc</p> <p>Original code:</p> <pre> do #N,label1 do #M,label2 BRKcc label2 label1 </pre> <p>Will be replaced by:</p> <pre> do #N, label1 do #M, label2 Jcc fix_brk_routine </pre>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	<u>Errata Description</u>	<u>Applies to Mask</u>
ED33 cont.	<pre> nop_before_label2 nop ; This instruction must be NOP. label2 label1 fix_brk_routine move #1,lc jmp nop_before_label2 ENDDO ----- Original code: do #M,label1 do #N,label2 ENDDO label2 label1 </pre> <p>Will be replaced by:</p> <pre> do #M, label1 do #N, label2 JMP fix_enddo_routine </pre>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	<u>Errata Description</u>	<u>Applies to Mask</u>
ED33 cont.	<pre> nop_after_jump NOP ; This instruction must be NOP. label2 label1 fix_enddo_routine move #1,lc move #nop_after_jump,la jmp nop_after_jump 2) DO FOREVER loops ===== BRKcc ----- Original code: do #M,label1 do forever,label2 BRKcc label2 label1 </pre>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	<u>Errata Description</u>	<u>Applies to Mask</u>
ED33 cont.	<p>Will be replaced by:</p> <pre> do #M,label1 do forever,label2 JScC fix_brk_forever_routine ; <--- note: JScC and not Jcc nop_before_label2 nop ; This instruction must be NOP. label2 label1 fix_brk_forever_routine move ssh,x:<..> ; <..> is some reserved not used address (for temporary data) move #nop_before_label2,ssh bclr #16,ssl ; move #1,lc rti ; <----- note: "rti" and not "rts" ! ENDDO ----- Original code: do #M,label1 </pre>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	<u>Errata Description</u>	<u>Applies to Mask</u>
ED33 cont.	<pre> do forever,label2 ENDDO label2 label1 Will be replaced by: do #M,label1 do forever,label2 JSR fix_enddo_routine ; <--- note: JSR and not JMP nop_after_jump NOP ; This instruction should be NOP label2 label1 fix_enddo_routine nop move #1,lc bclr #16,ssl move #nop_after_jump,la rti ; <--- note: "rti" and not "rts" </pre> <p>Pertains to: DSP56300 Family Manual, Section B-4.2, “General Do Restrictions.”</p>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	<u>Errata Description</u>	<u>Applies to Mask</u>
ED34	<p>Description (added 1/5/99; identified as a Documentation errata 2/1/99):</p> <p>When stack extension is enabled, the read result from stack may be improper if two previous executed instructions cause sequential read and write operations with SSH. Two cases are possible:</p> <p>Case 1:</p> <p>For the first executed instruction: move from SSH or bit manipulation on SSH (i.e. jclr, brclr, jset, brset, btst, bset, jsset, bsclr, jsclr).</p> <p>For the second executed instruction: move to SSH or bit manipulation on SSH (i.e. jsr, bsr, jscc, bscc).</p> <p>For the third executed instruction: an SSL or SSH read from the stack result may be improper - move from SSH or SSL or bit manipulation on SSH or SSL (i.e., bset, bclr, bchg, jclr, brclr, jset, brset, btst, bsset, jsset, bsclr, jsclr).</p> <p>Workaround:</p> <p>Add two NOP instructions before the third executed instruction.</p> <p>Case 2:</p> <p>For the first executed instruction: bit manipulation on SSH (i.e. bset, bclr, bchg).</p> <p>For the second executed instruction: an SSL or SSH read from the stack result may be improper - move from SSH or SSL or bit manipulation on SSH or SSL (i.e., bset, bclr, bchg, jclr, brclr, jset, brset, btst, bsset, jsset, bsclr, jsclr).</p> <p>Workaround:</p> <p>Add two NOP instructions before the second executed instruction.</p> <p>Pertains to: DSP56300 Family Manual, Appendix B, add a new section called "Stack Extension Enable Restrictions." Cover all cases. Also, in Section 6.3.11.15, add a cross reference to this new section.</p>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	<u>Errata Description</u>	<u>Applies to Mask</u>
ED37	<p>Description (added 4/19/99):</p> <p>In paragraph 6.1.1.11 on page 6-12 of the 301 User's Manual, there is an error, as follows:</p> <p>"HIRQ_ is asserted by the HI32 when a host interrupt request (recieve and/or transmit) is generated in the HI32"</p> <p>Workaround/correction:</p> <p>Should be:</p> <p>"HIRQ_ is asserted by the HI32 when a host interrupt request (receive and/or transmit) is generated in the HI32 (as described in paragraphs 6.2.1.1, 6.2.1.1 and 6.2.1.4)."</p>	0F92R
ED38	<p>Description (added 7/14/99):</p> <p>If Port A is used for external accesses, the BAT bits in the AAR3-0 registers must be initialized to the SRAM access type (i.e. BAT = 01) or to the DRAM access type (i.e. BAT = 10). To ensure proper operation of Port A, this initialization must occur even for an AAR register that is not used during any Port A access. Note that at reset, the BAT bits are initialized to 00.</p> <p>Pertains to: <i>DSP56300 Family Manual</i>, Port A Chapter (Chapter 9 in Revision 2), description of the BAT[1 -0] bits in the AAR3 - AAR0 registers. Also pertains to the core chapter in device-specific user's manuals that include a description of the AAR3 - AAR0 registers with bit definitions (usually Chapter 4).</p>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	Errata Description	Applies to Mask
ED40	<p>Description (added 11/11/99):</p> <p>When an instruction with all the following conditions follows a repeat instruction, then the last move will be corrupted.:</p> <ol style="list-style-type: none"> 1. The repeated instruction is from external memory. 2. The repeated instruction is a DALU instruction that includes 2 DAL registers, one as a source, and one as destination (e.g. tfr, add). 3. The repeated instruction has a double move in parallel to the DALU instruction: one move's source is the destination of the DALU instruction (causing a DALU interlock); the other move's destination is the source of the DALU instruction. <p>Example:</p> <pre> rep #number tfr x0,a x(r0)+,x0 a,y0 ; This instruction is from external memory _ _____ ----- -----> This is condition 3 second part. _____ -----> This is condition 3, first part - DALU interlock </pre> <p>In this example, the second iteration before the last, the "x(r0)+,x0" doesn't happen. On the first iteration before the last, the X0 register is fixed with the "x(r0)+,x0", but the "tfr x0,a" gets the wrong value from the previous iteration's X0. Thus, at the last iteration the A register is fixed with "tfr x0,a", but the "a,y0" transfers the wrong value from the previous iteration's A register to Y0.</p> <p>Workaround:</p> <ol style="list-style-type: none"> 1. Use the DO instruction instead; mask any necessary interrupts before the DO. 2. Run the REP instructions from internal memory. 3. Don't make DALU interlocks in the repeated instruction. After the repeat make the move. In the example above, all the "move a,y0" are redundant so it can be done in the next instruction: <pre> rep #number tfr x0,a x(r0)+,x0 move a,y0 </pre> <p>If no interrupts before the move is a must, mask the interrupts before the REP.</p> <p>Pertains to: <i>DSP56300 Family Manual, Rev. 2, Section A.3, "Instruction Sequence Restrictions."</i></p>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	<u>Errata Description</u>	<u>Applies to Mask</u>
ED41	<p>Description (reclassified as a documentation errata item on 3/22/2000):</p> <p>If the stack extension is enabled, the instructions listed below should not be placed as the next-to-last or as the last instruction of a DO loop (i.e., should not appear at LA-1 or LA).</p> <p>The instructions are:</p> <p>XY Memory Data Move (A-6.76) X Memory Move (A-6.71) Y Memory Move (A-6.73) Long Memory Data Move (A-6.75) Immediate Short Data Move (A-6.68) Register to Register Data Move (A-6.69) Address Register Update (A-6.70) X Memory and Register Data Move (A-6.72) Y Memory and Register Data Move (A-6.74) <i>Arithmetic Instructions that allow Parallel Moves listed above</i> IFcc and IFcc.U (A-6.41)</p> <p>Workaround:</p> <p>Insert a NOP or other instruction not listed above as the next-to-last and last instructions in the DO loop.</p> <p>Pertains to:</p> <p><i>DSP56300 Family Manual, Rev. 2, Section 5.4.3, "System Stack Configuration and Operation Registers."</i> To be noted immediately after the paragraph on nested hardware DO loops.</p>	0F92R
ED42	<p>Description (added on 3/22/2000)</p> <p>The DMA End-of-Block-Transfer interrupt cannot be used if DMA is operating in the mode in which DE is not cleared at the end of the block transfer (DTM = 100 or 101).</p> <p>Pertains to:</p> <p><i>DSP56300 Family Manual, Rev. 2, Section 10.4.1.2, "End-of-Block-Transfer Interrupt."</i> Also, Section 10.5.3.5, "DMA Control Registers (DCR[5-0])," discussion of bits 21 – 19 (DTM bits).</p>	0F92R



Freescale Semiconductor, Inc.

Chip Errata

DSP56301 Digital Signal Processor

Mask: 0F92R

Freescale Semiconductor, Inc.

Errata Number	Errata Description	Applies to Mask
ED46	<p>Description (added 12/10/2001):</p> <p>The following sequence gives erroneous results:</p> <ol style="list-style-type: none"> 1) A different slave on the bus terminates a transaction (for example, assertion of "stop"). 2) Immediately afterwards (no more than one PCI clock), the chip's memory space control/status register at PCI address ADDR is read in a single-word transaction. In this transaction, the chip drives to the bus the data corresponding to the register at PCI address ADDR+4, instead of the requested ADDR. <p>NOTE: ADDR is the PCI address of one of the following registers: HCTR (ADDR=\$10) , HSTR (ADDR=\$14), or HCVR (ADDR=\$18), and not the data register.</p> <p>Workaround:</p> <p>The user should find a way to set/clear at least one bit in the control/status registers to clearly differentiate between them. For example, you can set HNMI in the HCVR, as this bit will always be 0 in the HSTR. If NMI cannot be used, then HCVR{HV4,HV3,HV2} and HSTR{HF5,HF4,HF3} can be set in any combinations that distinguish between HCVR and HSTR data reads.</p> <p>Pertains to:</p> <p><i>DSP56301 User's Manual:</i> Put this errata text as a note in the description of the HCTR (p. 6-48), the HSTR (p. 6-57), and the HCVR (p. 6-59). These page numbers are for Revision 3 of the manual.</p> <p><i>DSP56305 User's Manual:</i> Put this errata text as a note in the description of the HCTR (p. 6-54), the HSTR (p. 6-68), and the HCVR (p. 6-72). These page numbers are for Revision 1 of the manual.</p>	0F92R
ED50	<p>Description (added 9/10/1996 as ES29; reclassified as a documentation erratum on 8/2/2002):</p> <p>When the SCI transmitter is used in Synchronous mode, the last bit of the transmitted byte might be truncated to the half of the serial cycle.</p> <p>Workaround: Not available.</p>	0F92R



Freescale Semiconductor, Inc.
Chip Errata
DSP56301 Digital Signal Processor
Mask: 0F92R

Freescale Semiconductor, Inc.