

MPC560xS_1M25V

Mask Set Errata



Mask Set Errata for Mask 1M25V

Revision History

This report applies to mask 1M25V for these products:

- MPC560xS
- MPC5602S
- MPC5604S
- MPC5606S

Table 1. Revision History

Revision	Date	Significant Changes
7	8/2022	The following errata were revised. <ul style="list-style-type: none"> • ERR011235 • ERR007394
6	1/2022	The following errata were revised. <ul style="list-style-type: none"> • ERR050459 • ERR050575
5	8/2021	The following errata were added. <ul style="list-style-type: none"> • ERR009682 • ERR003010 • ERR006726 • ERR004168 • ERR006976 • ERR050459 • ERR007274 • ERR011235 • ERR007394 • ERR009764 • ERR009976 • ERR003556 • ERR009978 • ERR006082 • ERR010755 • ERR005569 • ERR050575 • ERR011295

Table continues on the next page...

Table 1. Revision History (continued)

Revision	Date	Significant Changes
		<ul style="list-style-type: none"> • ERR011294 • ERR007688 • ERR011293 • ERR007120 • ERR007953 • ERR007322 • ERR008951 <p>The following errata were revised.</p> <ul style="list-style-type: none"> • ERR003570 • ERR002656
4	11/2011	<p>The following errata were added.</p> <ul style="list-style-type: none"> • ERR003570
3	11/2011	<p>Errata revision 23 August 2011</p> <p>Initial Revision</p>

Errata and Information Summary

Table 2. Errata and Information Summary

Erratum ID	Erratum Title
ERR004168	ADC: Abort switch aborts the ongoing injected channel as well as the upcoming normal channel
ERR003010	ADC: conversion chain failing after ABORT chain
ERR005569	ADC: The channel sequence order will be corrupted when a new normal conversion chain is started prior to completion of a pending normal conversion chain
ERR003194	ADC: Using the PIT trigger to start a conversion does not work under certain clock combination.
ERR003442	CMU monitor: FXOSC/FIRC and FMPLL/FIRC relation
ERR003449	DEBUG: Device may hang due to external or 'functional' reset while using debug handshaking mechanism
ERR003110	Debugging functionality could be lost when unsecuring a secured device.
ERR003556	DMA_MUX : Low Power Entry may not be completed when peripherals run on divided clock with DMA enabled mode
ERR003230	DSPI: Correct usage for Tx FIFO when continuous clock mode is enabled
ERR009976	DSPI: Incorrect data received by master with Modified transfer format enabled when using Continuous serial communication clock mode
ERR001082	DSPI: set up enough ASC time when MTFE=1 and CPHA=1

Table continues on the next page...

Table 2. Errata and Information Summary (continued)

Erratum ID	Erratum Title
ERR010755	DSPI: Transmit and Receive FIFO fill flags in status register is not cleared when DMA is improperly configured
ERR011235	EMIOS: Any Unified Channel running in OPWMB or OPWMCB mode may function improperly if the source counter bus is generated by Unified channel in MC mode
ERR050575	eMIOS: Any Unified Channel running in OPWMCB mode may function improperly if the lead or trail dead time insertion features is used and its timebase is generated by Unified channel in MCB mode
ERR011293	EMIOS: For any UC operating in OPWFMB mode the Channel Count register should not be written with a value greater than Channel B Data register value
ERR011295	EMIOS: In OPWFMB mode, A1/B1 registers do not get reloaded with A2/B2 register values if counter value returns 0x1 after counter wrap condition
ERR011294	EMIOS: OPWFMB and MCB mode counter rollover resets the counter to 0x0 instead of 0x1 as mentioned in the specification
ERR009978	eMIOS: Unexpected channel flag assertion during GPIO to MCB mode transition
ERR003324	FIRC - FIRC_CTL[TRIM] does not display correct trim value after reset
ERR002656	FlexCAN: Abort request blocks the CODE field
ERR007322	FlexCAN: Bus Off Interrupt bit is erroneously asserted when soft reset is performed while FlexCAN is in Bus Off state
ERR003407	FlexCAN: CAN Transmitter Stall in case of no Remote Frame in response to Tx packet with RTR=1
ERR002685	FlexCAN: Module Disable Mode functionality not described correctly
ERR008951	I2C: Attempting a start cycle while the bus is busy may generate a short clock pulse
ERR003021	LINFlex: Unexpected LIN timeout in slave mode
ERR006082	LINFlexD : LINS bits in LIN Status Register(LINSR) are not usable in UART mode.
ERR007274	LINFlexD: Consecutive headers received by LIN Slave triggers the LIN FSM to an unexpected state
ERR003219	MC_CGM: System clock may stop for case when target clock source stops during clock switching transition
ERR007394	MC_ME: Incorrect mode may be entered on low-power mode exit.
ERR003202	MC_ME: Invalid Configuration not flagged if PLL is on while OSC is off.
ERR003269	MC_ME: Peripheral clocks may get incorrectly disabled or enabled after entering debug mode
ERR003570	MC_ME: Possibility of Machine Check on Low-Power Mode Exit
ERR006976	MC_ME: SAFE mode not entered immediately on hardware-triggered SAFE mode request during STOP0 mode
ERR003321	MC_RGM: A non-monotonic ramp on the VDDR line can cause the RGM module to clear all flags in the DES register, meaning that code cannot tell if a POR has occurred.

Table continues on the next page...

Table 2. Errata and Information Summary (continued)

Erratum ID	Erratum Title
ERR003060	MC_RGM: SAFE mode exit may be possible even though condition causing the SAFE mode request has not been cleared
ERR007953	ME: All peripherals that will be disabled in the target mode must have their interrupt flags cleared prior to target mode entry
ERR006726	NPC: MCKO clock may be gated one clock period early when MCKO frequency is programmed as SYS_CLK/8.and gating is enabled
ERR007120	NZxC3: DQTAG implemented as variable length field in DQM message
ERR007688	RTC: An API interrupt may be triggered prematurely after programming the API timeout value
ERR009764	SARADC : DMA interface limitation depending on PBRIDGE/SARADC clock ratio
ERR003326	SIRC - SIRC_CTL[TRIM] does not display correct trim value after reset
ERR009682	SPI: Inconsistent loading of shift register data into the receive FIFO following an overflow event
ERR003119	SWT: SWT interrupt does not cause STOP0 mode exit
ERR050459	SXOSC: Clock output may contain extra clock pulses in Normal mode

Known Errata

ERR009682: SPI: Inconsistent loading of shift register data into the receive FIFO following an overflow event

Description

In the Serial Peripheral Interface (SPI) module, when both the receive FIFO and shift register are full (Receive FIFO Overflow Flag bit in Status Register is set (SR[RFOF] = 0b1)) and then the Clear Rx FIFO bit in Module Configuration Register (MCR[CLR_RXF]) is asserted to clear the receive FIFO, shift register data is loaded into the receive FIFO after the clear operation completes.

Workaround

1. Avoid a receive FIFO overflow condition (SR[RFOF] should never be 0b1). To do this, monitor the RX FIFO Counter field of the Status Register (SR[RXCTR]) which indicates the number of entries in receive FIFO and clear before the counter equals the FIFO depth.
2. Alternatively, after every receive FIFO clear operation (MCR[CLR_RXF] = 0b1) following a receive FIFO overflow (SR[RFOF] = 0b1) scenario, perform a single read from receive FIFO and discard the read data.

ERR003010: ADC: conversion chain failing after ABORT chain

Description

During a chain conversion while the ADC is in scan mode when ADC_MCR[ABORTCHAIN] is asserted the current chain will be aborted as expected. However, in the next scan the first conversion of the chain is performed twice and the last conversion of the chain is not performed.

Workaround

When aborting a chain conversion enable ADC_MCR[ABORTCHAIN] and disable ADC_MCR[START].

ADC_MCR[START] can be enabled when the abort is complete.

ERR006726: NPC: MCKO clock may be gated one clock period early when MCKO frequency is programmed as SYS_CLK/8.and gating is enabled

Description

The Nexus auxiliary message clock (MCKO) may be gated one clock period early when the MCKO frequency is programmed as SYS_CLK/8 in the Nexus Port Controller Port Configuration Register (NPC_PCR[MCKO_DIV]=111) and the MCKO gating function is enabled (NPC_PCR[MCKO_GT]=1). In this case, the last MCKO received by the tool prior to the gating will correspond to the END_MESSAGE state. The tool will not receive an MCKO to indicate the transition to the IDLE state, even though the NPC will transition to the IDLE state internally. Upon re-enabling of MCKO, the first MCKO edge will drive the Message Start/End Output (MSEO=11) and move the tool's state to IDLE.

Workaround

Expect to receive the MCKO edge corresponding to the IDLE state upon re-enabling of MCKO after MCKO has been gated.

ERR003060: MC_RGM: SAFE mode exit may be possible even though condition causing the SAFE mode request has not been cleared

Description

A SAFE mode exit should not be possible as long as any condition that caused a SAFE mode entry is still active. However, if the corresponding status flag in the RGM_FES register has been cleared, the SAFE mode exit may incorrectly occur even though the actual condition is still active.

Workaround

Software must clear the SAFE mode request condition at the source before clearing the corresponding RGM_FES flag. This will ensure that the condition is no longer active when the RGM_FES flag is cleared and thus the SAFE mode exit can occur under the correct conditions.

ERR003570: MC_ME: Possibility of Machine Check on Low-Power Mode Exit

Description

When executing from the flash and entering a Low-Power Mode (LPM) where the flash is in low-power or power-down mode, 2-4 clock cycles exist at the beginning of the RUNx to LPM transition during which a wakeup or interrupt will generate a checkstop due to the flash not being available on RUNx mode re-entry. This will cause either a checkstop reset or machine check interrupt.

Workaround

If the application must avoid the reset, two workarounds are suggested:

- 1) Configure the application to handle the machine check interrupt in RAM dealing with the problem only if it occurs
- 2) Configure the MCU to avoid the machine check interrupt, executing the transition into low power modes in RAM

There is no absolute requirement to work around the possibility of a checkstop reset if the application can accept the reset, and associated delays, and continue. In this event, the WKPU.WISR will not indicate the channel that triggered the wakeup though the F_CHKSTOP flag will indicate that the reset has occurred. The F_CHKSTOP flag could still be caused by other error conditions so the startup strategy from this condition should be considered alongside any pre-existing strategy for recovering from an F_CHKSTOP condition.

ERR004168: ADC: Abort switch aborts the ongoing injected channel as well as the upcoming normal channel

Description

If an Injected chain (jch1,jch2,jch3) is injected over a Normal chain (nch1,nch2,nch3,nch4) the Abort switch does not behave as expected.

Expected behavior:

Correct Case (without SW Abort on jch3): Nch1- Nch2(abort) -Jch1 - Jch2 - Jch3 - Nch2(restored) - Nch3 - Nch4

Correct Case(with SW Abort on jch3): Nch1 - Nch2(abort) -Jch1 - Jch2 - Jch3(abort) - Nch2(restored) - Nch3 - Nch4

Observed unexpected behavior:

Fault1 (without SW abort on jch3): Nch1 - Nch2(abort) - Jch1 - Jch2 - Jch3 - Nch3 - Nch4 (Nch2 not restored)

Fault2 (with SW abort on jch3): Nch1- Nch2 (abort) - Jch1 - Jch2 - Jch3(abort) - Nch4 (Nch2 not restored & Nch3 conversion skipped)

Workaround

It is possible to detect the unexpected behavior by using the CEOCFRx register. The CEOCFRx fields will not be set for a not restored or skipped channel, which indicates this issue has occurred. The CEOCFRx fields need to be checked before the next Normal chain execution (in scan mode). The CEOCFRx fields should be read by every ECH interrupt at the end of every chain execution.

ERR006976: MC_ME: SAFE mode not entered immediately on hardware-triggered SAFE mode request during STOP0 mode

Description

If a SAFE mode request is generated by the Reset Generation Module (MC_RGM) while the chip is in STOP0 mode, the chip does not immediately enter SAFE mode if STOP0 is configured as follows in the STOP0 Mode Configuration register (ME_STOP0_MC):

- the system clock is disabled (ME_STOP0_MC[SYSCLK] = 0b1111)
- the internal RC oscillator is enabled (ME_STOP0_MC[IRCON] = 0b1)

In this case, the chip will remain in STOP0 mode until an interrupt request or wakeup event occurs, causing the chip to return to its previous RUNx mode, after which the still pending SAFE mode request will cause the chip to enter SAFE mode.

Workaround

There are two possibilities.

1. Configure the internal RC oscillator to be disabled during STOP0 mode (ME_STOP0_MC[IRCON] = 0b0) if the device supports it.
2. Prior to entering STOP0 mode, configure all hardware-triggered SAFE mode requests that need to cause an immediate transition from STOP0 to SAFE mode to be interrupt requests. This is done in the MC_RGM's 'Functional' Event Alternate Request register (RGM_FEAR).

ERR050459: SXOSC: Clock output may contain extra clock pulses in Normal mode

Description

The 32 kHz Slow External Crystal Oscillator (SXOSC) may generate an extra clock pulse per clock period when configured in Normal mode using an external crystal. The SXOSC correctly generates positive clock edges aligned to the external crystal clock transitions but an extra clock pulse may be generated near the positive edge of the clock waveform. The SXOSC interface to the external crystal is not affected. This issue may only occur in the default Normal mode and operates as expected in Bypass mode (i.e. OSC_CTL[OSCBYP]=1).

The SXOSC clock source may be selected as the clock source for the Real Time Counter and Autonomous Periodic Interrupt (RTC/API) and also as the clock to be measured in the CMU Frequency Meter (via the CMU_FDR register). The RTC/API and CMU Frequency Meter counters may get an extra clock per SXOSC clock period causing a higher than expected count (affecting the calculated time or wakeup duration) or may theoretically cause a corrupted count value. The occurrence of the potential clock pulse may vary from clock period to clock period ranging from no extra clock pulse to one extra clock pulse per period. SXOSC may also be selected to be reflected to the CLKOUT pin. Worse case conditions to produce an extra clock pulse are lower temperatures.

Workaround

Use the SXOSC in Bypass mode instead of Normal mode by setting OSC_CTL[OSCBYP]. Bypass mode does not support an external crystal and thus an external clock source is needed.

Select other clock sources for the RTC/API and CMU Frequency Meter. The RTC/API supports other clock sources which include the 128 kHz Slow Internal RC Oscillator (SIRC), 16 MHz Fast Internal RC Oscillator (FIRC), and 4-16 MHz Fast External Crystal Oscillator (FXOSC).

ERR003324: FIRC - FIRC_CTL[TRIM] does not display correct trim value after reset

Description

The FIRC is trimmed during reset using a factory programmed value stored in flash. However after reset the trim value is not copied to FIRC_CTL[TRIM] as one would expect. Any read of FIRC_CTL[TRIM] will read 0 and in all likelihood this will not be the factory programmed value. Therefore any read-modify-write on the 32-bit register will set the FIRC to a trim value of 0 and not the factory programmed value.

Workaround

As the lower 16-bits of FIRC_CTL register only contain the TRIM field it is recommended that if the user wishes to program any other field they should only access the upper 16-bits of this register.

If the user wishes to calibrate the FIRC this should be performed using the CMU.

ERR003110: Debugging functionality could be lost when unsecuring a secured device.

Description

Providing the backdoor password via JTAG or via serial boot would unsecure the device, but on some devices may leave the Nexus interface and potentially the CPUs in an undetermined state.

Normal operation without a debugger is unaffected, debugging unsecured devices is also unaffected.

Workaround

A second connection attempt may be successful.

Boot in serial mode (using the Flash password), then execute code which unsecures the device. (The JTAG interface needs to be inactive while the unsecure happens.)

Implement a separate backdoor in application software. Once the software detects the custom backdoor sequence it can unlock the device via Flash write.

Leave device unsecured for debugging.

ERR007274: LINFlexD: Consecutive headers received by LIN Slave triggers the LIN FSM to an unexpected state

Description

As per the Local Interconnect Network (LIN) specification, the processing of one frame should be aborted by the detection of a new header sequence and the LIN Finite State Machine (FSM) should move to the protected identifier (PID) state. In the PID state, the LIN FSM waits for the detection of an eight bit frame identifier value.

In LINFlexD, if the LIN Slave receives a new header instead of data response corresponding to a previous header received, it triggers a framing error during the new header's reception and returns to IDLE state.

Workaround

The following three steps should be followed -

- 1) Configure slave to Set the MODE bit in the LIN Time-Out Control Status Register (LINTCSR[MODE]) to '0'.
- 2) Configure slave to Set Idle on Timeout in the LINTCSR[IOT] register to '1'. This causes the LIN Slave to go to an IDLE state before the next header arrives, which will be accepted without any framing error.
- 3) Configure master to wait for Frame maximum time (T Frame_Maximum as per LIN specifications) before sending the next header.

Note:

$$T_{Header_Nominal} = 34 * T_{Bit}$$
$$T_{Response_Nominal} = 10 * (N_{Data} + 1) * T_{Bit}$$
$$T_{Header_Maximum} = 1.4 * T_{Header_Nominal}$$
$$T_{Response_Maximum} = 1.4 * T_{Response_Nominal}$$
$$T_{Frame_Maximum} = T_{Header_Maximum} + T_{Response_Maximum}$$

where T_{Bit} is the nominal time required to transmit a bit and N_{Data} is number of bits sent.

ERR002656: FlexCAN: Abort request blocks the CODE field

Description

An Abort request to a transmit Message Buffer (TxMB) can block any write operation into its CODE field. Therefore, the TxMB cannot be aborted or deactivated until it completes a valid transmission (by winning the CAN bus arbitration and transmitting the contents of the TxMB).

Workaround

Instead of aborting the transmission, use deactivation instead.

Note that there is a chance that the deactivated TxMB can be transmitted without setting IFLAG and updating the CODE field if it is deactivated.

ERR011235: EMIOS: Any Unified Channel running in OPWMB or OPWMCB mode may function improperly if the source counter bus is generated by Unified channel in MC mode

Description

The Unified channel (UC) configured in Center Aligned Output Pulse Width Modulation Buffered (OPWMCB) or Output Pulse Width Modulation Buffered (OPWMB) modes is not working properly when it is sourced from the UC configured in Modulus Counter (MC) mode by setting the channel control register MODE bitfield to 0x10 or 0x11 and any of its pre-scalers (internal or global) divider ratio is higher than 1.

Workaround

When a counter bus is generated by the UC set in the MC mode with any pre-scaler (internal or global) divider ratio higher than 1, don't use this counter bus for the UC set in OPWMCB or OPWMB mode.

ERR007394: MC_ME: Incorrect mode may be entered on low-power mode exit.

Description

For the case when the Mode Entry (MC_ME) module is transitioning from a run mode (RUN0/1/2/3) to a low power mode (HALT/STOP/STANDBY*) if a wake-up or interrupt is detected one clock cycle after the second write to the Mode Control (ME_MCTL) register, the MC_ME will exit to the mode previous to the run mode that initiated the low power mode transition.

Example correct operation DRUN->RUN1-> RUN3->STOP->RUN3

Example failing operation DRUN->RUN1-> RUN3->STOP->RUN1

Note STANDBY mode is not available on all MPC56xx microcontrollers STANDBY mode is not available on all MPC56xx microcontrollers

Workaround

To ensure the application software returns to the run mode (RUN0/1/2/3) prior to the low power mode (HALT/STOP/STANDBY*) it is required that the RUNx mode prior to the low power mode is entered twice.

The following example code shows RUN3 mode entry prior to a low power mode transition.

```
ME.MCTL.R = 0x70005AF0; /* Enter RUN3 Mode & Key */
ME.MCTL.R = 0x7000A50F; /* Enter RUN3 Mode & Inverted Key */
while (ME.GS.B.S_MTRANS) {} /* Wait for RUN3 mode transition to complete */
ME.MCTL.R = 0x70005AF0; /* Enter RUN3 Mode & Key */
ME.MCTL.R = 0x7000A50F; /* Enter RUN3 Mode & Inverted Key */
while (ME.GS.B.S_MTRANS) {} /* Wait for RUN3 mode transition to complete */
/* Now that run mode has been entered twice can enter low power mode */
/* (HALT/STOP/STANDBY*) when desired. */
```

ERR009764: SARADC : DMA interface limitation depending on PBRIDGE/SARADC clock ratio

Description

The Successive Approximation Register Analog-to-Digital Converter (SARADC) modules can trigger a Direct Memory Access (DMA) request through the DMA Enable (DMAE) register interface.

When the SARADC clock (SAR_CLK) frequency is slower than half of the peripheral bridge (PBRIDGEx_CLK) clock frequency, the SARADC may trigger a spurious transfer request to the DMA module after the completion of a first valid transfer.

Workaround

Setting the DMA clear sequence enable (DCLR) bit in the DMAE register (DMAE[DCLR] = 1) forces the clearing of the DMA request on read access to the data register and therefore prevents the spurious DMA transfer request.

In case the Internal Channel Data Registers (ICDRn) are only accessed through DMA module (i.e. there are no bus accesses to ICDRn registers triggered by other than DMA bus master when the DMAE[DMAEN] bit is set), it is possible to configure DMAE[DCLR] bit to '1'. This will clear DMA transfer request on the first DMA read access, ensuring both that DMA triggered transfer will complete successfully and that no other spurious DMA request will be triggered.

This work-around can be applied when any of below condition can be met:

- frequency ratio PBRIDGEx_CLK/SAR_CLK <= 8/3
- PBRIDGEx_CLK is 40MHz and SAR_CLK >= 14MHz

ERR009976: DSPI: Incorrect data received by master with Modified transfer format enabled when using Continuous serial communication clock mode

Description

When the Deserial Serial Peripheral Interface (DSPI) module is configured as follows:

1. Master mode is enabled (Master/Slave Mode Select bit in Module Configuration Register is set (DSPI_MCR [MSTR] = 0b1))
2. Modified transfer format is enabled (Modified Transfer Format Enable bit in Module Configuration Register is set (DSPI_MCR [MTFE] = 0b1))
3. Continuous serial communication clock mode is enabled (Continuous SCK Enable bit in Module Configuration Register is set (DSPI_MCR [CONT_SCKE] = 0b1))

In this configuration if the frame size of the current frame is greater than the frame size of the next received frame, corrupt frames are received in two scenarios:

- a) Continuous Peripheral Chip Select Enable bit in PUSH TX FIFO Register is set (DSPI_PUSHR [CONT] = 0b1)
- b) DSPI_PUSHR [CONT] = 0b0 and lower significant bit of the frame is transferred first (LSB first bit in Clock and Transfer Attributes Register is set (DSPI_CTAR [LSBFE] = 0b1))

Workaround

To receive correct frames:

- a) When DSPI_PUSHR [CONT] = 0b1, configure the frame size of the current frame less than or equal to the frame size of the next frame (for all frames).
- b) When DSPI_PUSHR [CONT] = 0b0, configure DSPI_CTAR [LSBFE] = 0b0. Alternatively, configure the frame size of the current frame less than or equal to the frame size of the next frame (for all frames).

Make sure that for all received frames, the bits are read equal to their respective frame sizes and any extra bits during POP operation are masked.

ERR003449: DEBUG: Device may hang due to external or 'functional' reset while using debug handshaking mechanism

Description

If the low-power mode debug handshake has been enabled and an external reset or a 'functional' reset occurs while the device is in a low-power mode, the device will not exit reset.

Workaround

The NPC_PCR[LP_DBG_EN] bit must be cleared to ensure the correct reset sequence.

ERR003556: DMA_MUX : Low Power Entry may not be completed when peripherals run on divided clock with DMA enabled mode

Description

System may not enter into Low Power Mode (HALT/STOP/STANDBY) when all the below conditions are true simultaneously:

1. A Peripheral with DMA capability is programmed to work on divided clock.
2. Above peripheral is programmed to be stopped in Low Power Mode and active in RUN Mode.
3. Above Peripheral is active with DMA transfer while Software requests change to Low Power mode.

Workaround

Software should ensure that all the DMA enabled peripherals have completed their transfer before requesting Low Power mode Entry

ERR009978: eMIOS: Unexpected channel flag assertion during GPIO to MCB mode transition

Description

When changing an Enhanced Modular IO Subsystem (eMIOS) channel mode from General Purpose Input/Output (GPIO) to Modulus Counter Buffered (MCB) mode, the channel flag in the eMIOS Channel Status register (eMIOS_Sn[FLAG]) may incorrectly be asserted. This will cause an unexpected interrupt or DMA request if enabled for that channel.

Workaround

In order to change the channel mode from GPIO to MCB without causing an unexpected interrupt or DMA request, perform the following steps:

- (1) Clear the FLAG enable bit in the eMIOS Control register (eMIOS_Cn[FEN] = 0).
- (2) Change the channel mode (eMIOS_Cn[MODE]) to the desired MCB mode.
- (3) Clear the channel FLAG bit by writing '1' to the eMIOS Channel Status register FLAG field (eMIOS_Sn[FLAG] = 1).
- (4) Set the FLAG enable bit (eMIOS_Cn[FEN] = 1) to re-enable the channel interrupt or DMA request reaction.

ERR006082: LINFlexD : LINS bits in LIN Status Register(LINSR) are not usable in UART mode.

Description

When the LINFlexD module is used in the Universal Asynchronous Receiver/Transmitter (UART) mode, the LIN state bits (LINS3:0) in LIN Status Register (LINSR) always indicate the value zero. Therefore, these bits cannot be used to monitor the UART state.

Workaround

LINS bits should be used only in LIN mode.

ERR010755: DSPI: Transmit and Receive FIFO fill flags in status register is not cleared when DMA is improperly configured

Description

The Deserial/Serial Peripheral Interface Transmit and Receive First In/First Out (FIFO) buffers can request additional information to be transferred via the Direct Memory Access (DMA) module when either the Transmit or Receive FIFO Fill/Drain Flags are set in the DSPI Status Register (SR[TFFF/RDFD]). However, the Transmit Fill Flag indicates that at least 1 location each (2 bytes each) in the Transmit and Command FIFOs is available to be written. It does not indicate that the FIFO is empty. Similarly, Receive FIFO fill flag only indicates at least 1 location (2 bytes) of the FIFO is available to be read. It does not indicate that the FIFO is full. If the DMA is configured to transfer more than 1 FIFO location size of data, the FIFO Fill/Drain Flags may not be properly cleared indicating that the FIFO is not full even when the FIFO is actually full (for Transmit FIFO) and not empty when the FIFO is actually empty (for Receive FIFO).

Workaround

Properly configure the DMA to fill/drain only 2 bytes to Transmit, Command and Receive FIFOs. Use the DMA loop to transfer more data if needed.

ERR003230: DSPI: Correct usage for Tx FIFO when continuous clock mode is enabled

Description

If the FIFO is enabled with continuous Serial Communication Clock (SCK) mode, a change in SCK frequency may occur if the Tx FIFO is not cleared and the Clock and Transfer Attributes Register 0 (CTAR0) is not used.

Workaround

When in continuous SCK mode, always use CTAR0 for the SPI transfer and always clear the TX-FIFO using the Clear TX FIFO (CLR_TXF) field of the Module Configuration Register (MCR) before initiating transfer.

ERR003442: CMU monitor: FXOSC/FIRC and FMPLL/FIRC relation

Description

Functional CMU monitoring can only be guaranteed when the following conditions are met:

- FXOSC frequency must be greater than $(FIRC / 2^{RCDIV}) + 0.5\text{MHz}$ in order to guarantee correct FXOSC monitoring
- FMPLL frequency must be greater than $(FIRC / 4) + 0.5\text{MHz}$ in order to guarantee correct FMPLL monitoring

Workaround

Refer to description

ERR003119: SWT: SWT interrupt does not cause STOP0 mode exit

Description

While in STOP0 mode, if the SWT is configured to generate an interrupt and the system clock is disabled ($ME_STOP0_MC[SYSCLK] = 0xF$), a SWT interrupt event will not trigger an exit from STOP0 mode.

Other internal or external wakeup events (RTC, API, WKUP pins) are not affected and will trigger a STOP0 exit independent of the $ME_STOP0_MC[SYSCLK]$ configuration.

Workaround

If a SWT interrupt is to be used to wake the device during STOP0 mode, software may not disable the system clock ($ME_STOP0_MC[SYSCLK] \neq 0xF$).

ERR002685: FlexCAN: Module Disable Mode functionality not described correctly

Description

Module Disable Mode functionality is described as the FlexCAN block is directly responsible for shutting down the clocks for both CAN Protocol Interface (CPI) and Message Buffer Management (MBM) sub-modules. In fact, FlexCAN requests this action to an external logic.

Workaround

In FlexCAN documentation chapter:

Section "Modes of Operation", bullet "Module Disable Mode":

Where is written:

"This low power mode is entered when the MDIS bit in the MCR Register is asserted. When disabled, the module shuts down the clocks to the CAN Protocol Interface and Message Buffer Management sub-modules.."

The correct description is:

"This low power mode is entered when the MDIS bit in the MCR Register is asserted by the CPU. When disabled, the module requests to disable the clocks to the CAN Protocol Interface and Message Buffer Management sub-modules."

Section "Modes of Operation Details", Sub-section "Module Disable Mode":

Where is written:

"This low power mode is entered when the MDIS bit in the MCR Register is asserted. If the module is disabled during Freeze Mode, it shuts down the clocks to the CPI and MBM sub-modules, sets the LPM_ACK bit and negates the FRZ_ACK bit.."

The correct description is:

"This low power mode is entered when the MDIS bit in the MCR Register is asserted. If the module is disabled during Freeze Mode, it requests to disable the clocks to the CAN Protocol Interface (CPI) and Message Buffer Management (MBM) sub-modules, sets the LPM_ACK bit and negates the FRZ_ACK bit."

ERR005569: ADC: The channel sequence order will be corrupted when a new normal conversion chain is started prior to completion of a pending normal conversion chain

Description

If One shot mode is configured in the Main Configuration Register (MCR[MODE] = 0) the chained channels are automatically enabled in the Normal Conversion Mask Register 0 (NCMR0). If the programmer initiates a new chain normal conversion, by setting MCR[NSTART] = 0x1, before the previous chain conversion finishes, the new chained normal conversion will not follow the requested sequence of converted channels.

For example, if a chained normal conversion sequence includes three channels in following sequence: channel0, channel1 and channel2, the conversion sequence is started by MCR[NSTART] = 0x1. The software re-starts the next conversion sequence when MCR[NSTART] is set to 0x1 just before the current conversion sequence finishes.

The conversion sequence should be: channel0, channel1, channel2, channel0, channel1, channel2.

However, the conversion sequence observed will be: channel0, channel1, channel2, channel1, channel1, channel2. Channel0 is replaced by channel1 in the second chain conversion and channel1 is converted twice.

Workaround

Ensure a new conversion sequence is not started when a current conversion is ongoing. This can be ensured by issuing the new conversion setting MCR[NSTART] only when MSR[NSTART] = 0.

Note: MSR[NSTART] indicates the present status of conversion. MSR[NSTART] = 1 means that a conversion is ongoing and MSR[NSTART] = 0 means that the previous conversion is finished.

ERR050575: eMIOS: Any Unified Channel running in OPWMCB mode may function improperly if the lead or trail dead time insertion features is used and its timebase is generated by Unified channel in MCB mode

Description

The Unified channel (UC) configured in Center Aligned Output Pulse Width Modulation Buffered (OPWMCB) mode is not working properly when:

1. It's timebase is sourced from the UC configured in Modulus Counter Buffered (MCB) mode.
2. The lead or trail dead time insertion features is used.
3. Its channel prescaler is different than timebase channel prescaler.

Workaround

Channel configured in OPWMCB mode with lead or trail dead time insertion features enabled must have channel prescaler equal to the timebase channel prescaler configured in MCB mode.

ERR011295: EMIOS: In OPWFMB mode, A1/B1 registers do not get reloaded with A2/B2 register values if counter value returns 0x1 after counter wrap condition

Description

In Output Pulse-Width and Frequency Modulation Buffered (OPWFMB) mode, A1/B1 registers do not get reloaded with A2/B2 register values if counter value returns 0x1 after counter wrap condition.

In order to avoid the counter wrap condition make sure internal counter value is within the 0x1 to B1 register value range when the OPWFMB mode is entered. Also overwriting of Channel Count register by forcing 'freeze' in OPWFMB mode should not take internal counter outside 0x1 to B register value.

Workaround

In order to avoid the counter wrap condition:

1. Make sure internal counter value is within the 0x1 to (B1 register) value range when the OPWFMB mode is entered.
2. Overwrite of Channel Count register by forcing 'freeze' in OPWFMB mode should not be outside the range of 0x1 to (B register) value.

ERR003326: SIRC - SIRC_CTL[TRIM] does not display correct trim value after reset

Description

The SIRC is trimmed during reset using a factory programmed value stored in flash. After reset this trim value is not visible at SIRCRC_CTL[TRIM]. Therefore any read-modify-write on the 32-bit register will potentially set the SIRC to an unoptimised trim value.

Workaround

As the lower 16-bits of SIRC_CTL register only contain the TRIM field it is recommended that if the user wishes to program any other field they should only access the upper 16-bits of this register.

If the user wishes to calibrate the SIRC this should be performed using the CMU.

ERR011294: EMIOS: OPWFMB and MCB mode counter rollover resets the counter to 0x0 instead of 0x1 as mentioned in the specification

Description

When the enhanced Modular Input/Output System (eMIOS) is used in Output Pulse-Width and Frequency Modulation Buffered (OPWFMB) or Modulus Counter Buffered (MCB) modes, when the counter rolls over, the counter returns to 0x0 instead of 0x1 as specified in the reference manual.

Workaround

In order to avoid the counter wrap condition:

1. Make sure internal counter value is within the 0x1 to (B1 register) value range when the OPWFMB mode is entered.
2. Overwrite of Channel Count register by forcing 'freeze' in OPWFMB mode should not be outside the range of 0x1 to (B register) value.

ERR007688: RTC: An API interrupt may be triggered prematurely after programming the API timeout value

Description

When the API is enabled (RTCC[APIEN]), the API interrupt flag is enabled (RTCC[APIIE]) and the API timeout value (RTCC[APIVAL]) is programmed the next API interrupt may be triggered before the programmed API timeout value. Successive API Interrupts will be triggered at the correct time interval.

Workaround

The user must not use the first API interrupt for critical timing tasks.

ERR003219: MC_CGM: System clock may stop for case when target clock source stops during clock switching transition

Description

The clock switching is a two step process. The availability of the target clock is first verified. Then the system clock is switched to the new target clock source within two target clock cycles.

For the case when the FXOSC stops during the required two cycles, the switching process may not complete, causing the system clock to stop and prevent further clock switching. This may happen if one of the following cases occurs while the system clock source is switching to FXOSC:

- FXOSC oscillator failure
- SAFE mode request occurs, as this mode will immediately switch OFF the FXOSC (refer to ME_SAFE_MC register configuration)

Workaround

The device is able to recover through any reset event ('functional', 'destructive', internal or external), so typically either the SWT (internal watchdog) will generate a reset or, in case it is used in the application, the external watchdog will generate an external reset. In all cases the devices will restart properly after reset.

To reduce the probability that this issue occurs in the application, disable SAFE mode transitions when the device is executing a mode transition with the FXOSC as the system clock source in the target mode.

ERR011293: EMIOS: For any UC operating in OPWFMB mode the Channel Count register should not be written with a value greater than Channel B Data register value

Description

For any Unified Channel (UC) running in Output Pulse-Width and Frequency Modulation Buffered (OPWFMB) mode, Channel Control Register MODE bitfield = 7'h1011000 or 7'h1011010, the internal counter runs from 0x1 to Channel B Data register value.

The internal counter can be overwritten by software using the Channel Count register during 'freeze' operation.

If a counter wrap occurs due to overwriting of the counter with a value greater than its expiry value (B Data Register value); then the output signal behavior cannot be guaranteed.

Workaround

For any UC operating in OPWFMB mode the Channel Count register should not be written with a value greater than Channel B Data register value.

ERR003321: MC_RGM: A non-monotonic ramp on the VDDR line can cause the RGM module to clear all flags in the DES register, meaning that code cannot tell if a POR has occurred.

Description

When system powers up, the 5V regulator supply (VDDR) shows a non-linearity in ramp up which coincides with the ramp-up of the 1.2V supply (VDD12). When a "slow" ramp is used the VDDR can dip to the LVDHV3 (2.9V - 2.6V) level causing it to re-fire.

With a "fast" ramp rate, the non linearity on 5V VDDR is shifted it does not dip to the LVDHV3 level. The F_POR flag is reported correctly in this instance.

If the LVDHV3 is re-fired just after the LVDLVCOR is released, then the POR & LVDHV3 flags will not be captured by the RGM. This is possible due to the soft startup mechanism of the voltage regulator power up profile.

This errata only affects the flag circuit and not a the device initialization. Device initializes correctly under all conditions.

Workaround

Potential solutions to avoid non-linearity from triggering LVDHV3:

- 1) Ensure that non linearity on VDDR is < 100mV . This is the hysteresis limit of the device. Board regulator should be chosen accordingly.
- 2) Make sure that VDDR ramp rate is fast enough. Criteria: when the VDD12 reaches its LVD levels, VDDR should have got enough margin from the LVDHV3 levels.

Software Workaround:

In the event of a boot where neither the F_POR or LVD27/LVD12 flags are set, the SRAM should be checked for ECC errors. If ECC errors are detected then it can be assumed that a POR has occurred.

ERR003202: MC_ME: Invalid Configuration not flagged if PLL is on while OSC is off.

Description

PLL clock generation requires oscillator to be on. Mode configuration in which PLLON bit is "1" and OSCON bit is "0" is an invalid mode configuration. When ME_XXX_MC registers are attempted with such an invalid configuration, ME_IS.I_ICONF is not getting set which is wrong. Eventually the mode transition did not complete and system hangs.

Workaround

Always program Oscillator to be on when PLL is required.

ERR007120: NZxC3: DQTAG implemented as variable length field in DQM message

Description

The e200zx core implements the Data Tag (DQTAG) field of the Nexus Data Acquisition Message (DQM) as a variable length packet instead of an 8-bit fixed length packet. This may result in an extra clock ("beat") in the DQM trace message depending on the Nexus port width selected for the device.

Workaround

Tools should decode the DQTAG field as a variable length packet instead of a fixed length packet.

ERR001082: DSPI: set up enough ASC time when MTFE=1 and CPHA=1

Description

When the DSPI is being used in the Modified Transfer Format mode (DSPI_MCR[MTFE]=1) with the clock phase set for Data changing on the leading edge of the clock and captured on the following edge in the DSPI Clock and Transfer Attributes Register (DSPI_CTARn[CPHA]=1), if the After SCK delay scaler (ASC) time is set to less than 1/2 SCK clock period the DSPI may not complete the transaction - the TCF flag will not be set, serial data will not received, and last transmitted bit can be truncated.

Workaround

If the Modified Transfer Format mode is required DSPI_MCR[MTFE]=1 with the clock phase set for serial data changing on the leading edge of the clock and captured on the following edge in the SCK clock (Transfer Attributes Register (DSPI_CTARn[CPHA]=1) make sure that the ASC time is set to be longer than half SCK clock period.

ERR007953: ME: All peripherals that will be disabled in the target mode must have their interrupt flags cleared prior to target mode entry

Description

Before entering the target mode, software must ensure that all interrupt flags are cleared for those peripheral that are programmed to be disabled in the target mode. A pending interrupt from these peripherals at target mode entry will block the mode transition or possibly lead to unspecified behaviour.

Workaround

For those peripherals that are to be disabled in the target mode the user has 2 options:

1. Mask those peripheral interrupts and clear the peripheral interrupt flags prior to the target mode request.
2. Through the target mode request ensure that all those peripheral interrupts can be serviced by the core.

ERR007322: FlexCAN: Bus Off Interrupt bit is erroneously asserted when soft reset is performed while FlexCAN is in Bus Off state

Description

Under normal operation, when FlexCAN enters in Bus Off state, a Bus Off Interrupt is issued to the CPU if the Bus Off Mask bit (CTRL[BOFF_MSK]) in the Control Register is set. In consequence, the CPU services the interrupt and clears the ESR[BOFF_INT] flag in the Error and Status Register to turn off the Bus Off Interrupt.

In continuation, if the CPU performs a soft reset after servicing the bus off interrupt request, by either requesting a global soft reset or by asserting the MCR[SOFT_RST] bit in the Module Configuration Register, once MCR[SOFT_RST] bit transitions from 1 to 0 to acknowledge the soft reset completion, the ESR[BOFF_INT] flag (and therefore the Bus Off Interrupt) is re-asserted.

The defect under consideration is the erroneous value of Bus Off flag after soft reset under the scenario described in the previous paragraph.

The Fault Confinement State (ESR[FLT_CONF] bit field in the Error and Status Register) changes from 0b11 to 0b00 by the soft reset, but gets back to 0b11 again for a short period, resuming after certain time to the expected Error Active state (0b00). However, this late correct state does not reflect the correct ESR[BOFF_INT] flag which stays in a wrong value and in consequence may trigger a new interrupt service.

Workaround

To prevent the occurrence of the erroneous Bus Off flag (and eventual Bus Off Interrupt) the following soft reset procedure must be used:

1. Clear CTRL[BOFF_MSK] bit in the Control Register (optional step in case the Bus Off Interrupt is enabled).
2. Set MCR[SOFT_RST] bit in the Module Configuration Register.
3. Poll MCR[SOFT_RST] bit in the Module Configuration Register until this bit is cleared.
4. Wait for 4 peripheral clocks.
5. Poll ESR[FLTCONF] bit in the Error and Status Register until this field is equal to 0b00.
6. Write "1" to clear the ESR[BOFF_INT] bit in the Error and Status Register.
7. Set CTRL[BOFF_MSK] bit in the Control Register (optional step in case the Bus Off Interrupt is enabled).

ERR008951: I2C: Attempting a start cycle while the bus is busy may generate a short clock pulse

Description

When the I2C (Inter-Integrated Circuit) is operating in a multi-master network and a start cycle is attempted by the I2C device when the bus is busy, the attempting master will lose arbitration as expected but a short extra clock cycle is generated in the bus. After losing arbitration, the master switches to slave mode but it does not detect the short clock pulse. The acknowledge signal is expected at the ninth clock by the current bus master but it is not sent as expected due to the undetected short clock pulse.

Workaround

Software must ensure that the I2C BUS is idle by checking the bus busy bit in the I2C Bus Status Register (I2C_IBSR.IBB) before switching to master mode and attempting a Start cycle.

ERR003021: LINFlex: Unexpected LIN timeout in slave mode

Description

If the LINFlex is configured in LIN slave mode, an unexpected LIN timeout event (LINESR[OCF]) may occur during LIN Break reception.

Workaround

It is recommended to disable this functionality during LINFlex initialization by clearing LINTCSR[IOT] and LINIER[OCIE] bits, and ignore timeout events.

ERR003194: ADC: Using the PIT trigger to start a conversion does not work under certain clock combination.

Description

It is possible for the PIT to start an ADC conversion by enabling the TRGEN bit in the ADC MCR register. However, this does not work when the clock to the ADC is slower than the system clock.

The clock to the ADC is configured in the CGM_SC_DC2 register in the CGM. The system clock is configured through the Mode Entry module

Workaround

There are two possible workarounds:

1. Trigger conversions by writing to the ADC registers directly
2. When using the PIT trigger make sure that ADC is running at same clock frequency as the system clock.

ERR003407: FlexCAN: CAN Transmitter Stall in case of no Remote Frame in response to Tx packet with RTR=1

Description

FlexCAN does not transmit an expected message when the same node detects an incoming Remote Request message asking for any remote answer.

The issue happens when two specific conditions occur:

- 1) The Message Buffer (MB) configured for remote answer (with code "a") is the last MB. The last MB is specified by Maximum MB field in the Module Configuration Register (MCR[MAXMB]).

2) The incoming Remote Request message does not match its ID against the last MB ID.

While an incoming Remote Request message is being received, the FlexCAN also scans the transmit (Tx) MBs to select the one with the higher priority for the next bus arbitration. It is expected that by the Intermission field it ends up with a selected candidate (winner). The coincidence of conditions (1) and (2) above creates an internal corner case that cancels the Tx winner and therefore no message will be selected for transmission in the next frame. This gives the appearance that the FlexCAN transmitter is stalled or "stops transmitting".

The problem can be detectable only if the message traffic ceases and the CAN bus enters into Idle state after the described sequence of events.

There is NO ISSUE if any of the conditions below holds:

- a) The incoming message matches the remote answer MB with code "a".
- b) The MB configured as remote answer with code "a" is not the last one.
- c) Any MB (despite of being Tx or Rx) is reconfigured (by writing its CS field) just after the Intermission field.
- d) A new incoming message sent by any external node starts just after the Intermission field.

Workaround

Do not configure the last MB as a Remote Answer (with code "a").

ERR003269: MC_ME: Peripheral clocks may get incorrectly disabled or enabled after entering debug mode

Description

If ME_RUN_PCx, ME_LP_PCx, ME_PCTLx registers are changed to enable or disable a peripheral, and the device enters debug mode before a subsequent mode transition, the peripheral clock gets enabled or disabled according to the new configuration programmed. Also ME_PSx registers will report incorrect status as the peripheral clock status is not expected to change on debug mode entry.

Workaround

After modifying any of the ME_RUN_PCx, ME_LP_PCx, ME_PCTLx registers, request a mode change and wait for the mode change to be completed before entering debug mode in order to have consistent behaviour on peripheral clock control process and clock status reporting in the ME_PSx registers.

Legal information

Definitions

Draft — A draft status on a document indicates that the content is still under internal review and subject to formal approval, which may result in modifications or additions. NXP Semiconductors does not give any representations or warranties as to the accuracy or completeness of information included in a draft version of a document and shall have no liability for the consequences of use of such information.

Disclaimers

Limited warranty and liability — Information in this document is believed to be accurate and reliable. However, NXP Semiconductors does not give any representations or warranties, expressed or implied, as to the accuracy or completeness of such information and shall have no liability for the consequences of use of such information. NXP Semiconductors takes no responsibility for the content in this document if provided by an information source outside of NXP Semiconductors.

In no event shall NXP Semiconductors be liable for any indirect, incidental, punitive, special or consequential damages (including - without limitation - lost profits, lost savings, business interruption, costs related to the removal or replacement of any products or rework charges) whether or not such damages are based on tort (including negligence), warranty, breach of contract or any other legal theory.

Notwithstanding any damages that customer might incur for any reason whatsoever, NXP Semiconductors' aggregate and cumulative liability towards customer for the products described herein shall be limited in accordance with the Terms and conditions of commercial sale of NXP Semiconductors.

Right to make changes — NXP Semiconductors reserves the right to make changes to information published in this document, including without limitation specifications and product descriptions, at any time and without notice. This document supersedes and replaces all information supplied prior to the publication hereof.

Suitability for use — NXP Semiconductors products are not designed, authorized or warranted to be suitable for use in life support, life-critical or safety-critical systems or equipment, nor in applications where failure or malfunction of an NXP Semiconductors product can reasonably be expected to result in personal injury, death or severe property or environmental damage. NXP Semiconductors and its suppliers accept no liability for inclusion and/or use of NXP Semiconductors products in such equipment or applications and therefore such inclusion and/or use is at the customer's own risk.

Applications — Applications that are described herein for any of these products are for illustrative purposes only. NXP Semiconductors makes no representation or warranty that such applications will be suitable for the specified use without further testing or modification.

Customers are responsible for the design and operation of their applications and products using NXP Semiconductors products, and NXP Semiconductors accepts no liability for any assistance with applications or customer product design. It is customer's sole responsibility to determine whether the NXP Semiconductors product is suitable and fit for the customer's applications and products planned, as well as for the planned application and use of customer's third party customer(s). Customers should provide appropriate design and operating safeguards to minimize the risks associated with their applications and products.

NXP Semiconductors does not accept any liability related to any default, damage, costs or problem which is based on any weakness or default in the customer's applications or products, or the application or use by customer's third party customer(s). Customer is responsible for doing all necessary testing for the customer's applications and products using NXP Semiconductors products in order to avoid a default of the applications and the products or of the application or use by customer's third party customer(s). NXP does not accept any liability in this respect.

Terms and conditions of commercial sale — NXP Semiconductors products are sold subject to the general terms and conditions of commercial sale, as published at <http://www.nxp.com/profile/terms>, unless otherwise agreed in a valid written individual agreement. In case an individual agreement is concluded only the terms and conditions of the respective agreement shall apply. NXP Semiconductors hereby expressly objects to applying the customer's general terms and conditions with regard to the purchase of NXP Semiconductors products by customer.

Suitability for use in automotive applications — This NXP product has been qualified for use in automotive applications. If this product is used by customer in the development of, or for incorporation into, products or services (a) used in safety critical applications or (b) in which failure could lead to death, personal injury, or severe physical or environmental damage (such products and services hereinafter referred to as "Critical Applications"), then customer makes the ultimate design decisions regarding its products and is solely responsible for compliance with all legal, regulatory, safety, and security related requirements concerning its products, regardless of any information or support that may be provided by NXP. As such, customer assumes all risk related to use of any products in Critical Applications and NXP and its suppliers shall not be liable for any such use by customer. Accordingly, customer will indemnify and hold NXP harmless from any claims, liabilities, damages and associated costs and expenses (including attorneys' fees) that NXP may incur related to customer's incorporation of any product in a Critical Application.

Export control — This document as well as the item(s) described herein may be subject to export control regulations. Export might require a prior authorization from competent authorities.

Translations — A non-English (translated) version of a document, including the legal information in that document, is for reference only. The English version shall prevail in case of any discrepancy between the translated and English versions.

Security — Customer understands that all NXP products may be subject to unidentified vulnerabilities or may support established security standards or specifications with known limitations. Customer is responsible for the design and operation of its applications and products throughout their lifecycles to reduce the effect of these vulnerabilities on customer's applications and products. Customer's responsibility also extends to other open and/or proprietary technologies supported by NXP products for use in customer's applications. NXP accepts no liability for any vulnerability. Customer should regularly check security updates from NXP and follow up appropriately.

Customer shall select products with security features that best meet rules, regulations, and standards of the intended application and make the ultimate design decisions regarding its products and is solely responsible for compliance with all legal, regulatory, and security related requirements concerning its products, regardless of any information or support that may be provided by NXP.

NXP has a Product Security Incident Response Team (PSIRT) (reachable at PSIRT@nxp.com) that manages the investigation, reporting, and solution release to security vulnerabilities of NXP products.

Trademarks

Notice: All referenced brands, product names, service names, and trademarks are the property of their respective owners.

NXP — wordmark and logo are trademarks of NXP B.V.

Please be aware that important notices concerning this document and the product(s) described herein, have been included in section 'Legal information'.

© NXP B.V. 2022.

All rights reserved.

For more information, please visit: <http://www.nxp.com>

For sales office addresses, please send an email to: salesaddresses@nxp.com

Date of release: 8/2022

Document identifier: MPC560xS_1M25V