

Silicon Errata for the MSC8102 Processor, Mask 1K94M

This document presents the errata for the 1K94M mask of the Freescale MSC8102 device. The errata are classified and numbered, and each erratum is provided with a description and workarounds.

Silicon Errata

Errata Number	Errata Description	Mask
QSE1	Prefetch Fault Date Added: 2/2002 Description: In PPC-Little-Endian mode, a 32-bit bus prefetch fault cause a prefetch in the wrong order. Impact: The option to use prefetch is eliminated in this mode (32-bit PPC little endian), causing a delay in data reads Workaround: Disable the prefetch when this mode is in use. System Number: 7588	1K94M
QSE2	DSI Protocol Violation Date Added: 2/2002 Description: During 64-bit read accesses in synchronous mode, the DSI may violate the DSI protocol, causing data loss or invalid bus behavior. Impact: Eliminates the use of 64-bit burst read reads in synchronous mode (a minor impact on DSI throughput). Fix Plan: HIP8 Version of MSC8102, which is the MSC8122 device Workaround: Do not perform burst read when at 64bit synchronous mode. System Number: 7434	1K94M
QSE9	Synchronous, 64-Bit Mode DSI Protocol Violation Date Added: 4/15/2002 Description: In a DSP Farm application running in Synchronous 64-bit mode, when a read or write is performed to one DSI after a write burst is performed to another DSI, a contention may occur on the HTA_B signal. This contention may cause the DSI to violate DSI protocol, resulting in data loss or bus invalid behavior. Impact: Eliminates the use of a burst write in 64-bit at synchronous mode in DSP farm applications (a minor impact on DSI throughput). Fix Plan: HIP8 Version of MSC8102, which is the MSC8122 device Workaround: Do not perform a burst write in Synchronous 64-bit mode in DSP farm applications. System Number: 7852	1K94M

Silicon Errata

Errata Number	Errata Description	Mask
QSE12	Write Immediate Through Write Buffer Date Added: 5/2002 Description: If the SC140 core initiates a “write immediate” (see EQBS chapter) when the Write Buffer is not empty, the SC140 core may continue before the end of the write. The SC140 core may continue when the data of the write is still in the Write Buffer. The write eventually arrives at its destination, but there is no guarantee of synchronization with the SC140 core. Impact: “Write immediate” through the Write Buffer may not freeze the SC140 core. Fix Plan: HIP8 Version of MSC8102, which is the MSC8122 device Workaround: <i>Option 1:</i> Write 2 “write immediate” at the same execution set. <i>Option 2:</i> Write “write immediate” with read from external memory, at the same execution set. <i>Option 3:</i> Write “write immediate” when the Write-Buffer is empty. <i>Option 4:</i> Do not use write immediate through the Write Buffer. If it is necessary, turn the Write Buffer off. Then, all writes are immediate. System Number: 7896	1K94M
QSE14	Incorrect Masking of Machine Check Interrupt Date Added: 5/2002 Description: Incorrect Masking of Machine Check Interrupt (MCP). Impact: Because of data errors (parity / ECC), the MCP is masked by the SYPCR[30]:SWRI bit. Fix Plan: HIP8 Version of MSC8102, which is the MSC8122 device Workaround: Clear SYPCR[30]:SWRI to get a data error indication. Clearing of SWRI also means an MCP generation instead of a hard reset generation on Software Watchdog time-out. System Number: 3695	1K94M
QSE17	Attributes are Not Captured Due to Data Parity Error Date Added: 5/2002 Description: When a data parity error occurs, the Machine Check Procedure (MCP) is generated, but the transaction attributes, such as address and TC, are not captured in the TESCR registers. Impact: Cannot locate the initial cause of the parity error. Fix Plan: HIP8 Version of MSC8102, which is the MSC8122 device Workaround: None. System Number: 7775	1K94M
QSE24	Illegal Execution Set Freezes SC140 Core Date Added: 5/2002 Date Revised: 4/2003 Description: In rare situations, an illegal execution set fetched by the SC140 core can alter the settings of system registers or cause the SC140 core to enter a freeze state that can only be released by reset. Impact: The SC140 illegal instruction trap does not provide 100 percent protection against execution of illegal instructions. Workaround: No workaround available. System Number: 7541	1K94M

Silicon Errata

Errata Number	Errata Description	Mask
QSE26	Bus Error Interrupt After Access to Non-valid Address Date Added: 5/2002 Description: Bus error interrupts are for recognizing accesses from the SC140 core that are for non-valid addresses in internal memory space. A non-valid address is an address that is not mapped in the internal memory system (EQBS, EOnCE, L1 Memory). In some cases, the bus error interrupt does not occur after access to a non-valid address in internal memory. Impact: In some cases a bus error interrupt is not asserted. Workaround: No workaround available. System Number: 7894, 7693, 7864	1K94M
QSE30	Bus Monitor Asserts Spurious $\overline{\text{TEA}}$ After Address Retry Date Added: 6/2002 Description: The bus monitor does not recognize the competition of an Address Retry transaction and will assert $\overline{\text{TEA}}$ if there is no bus activity for a time equal to the expiration time. Fix Plan: HIP8 Version of MSC8102, which is the MSC8122 device Workaround: Disable the bus monitor in systems where Address Retry cycles are used. System Number: 6997	1K94M
QSE31	Use Only Compliant Arbiter Date Added: 6/2002 Description: This is a compatibility note. An external arbiter must assert DBG in the same clock in which TS is asserted (there may be a one clock delay if the PPC_ACR[2]:DBGD bit is set. However, after reset, this bit is not set by default). Some external arbiters violate this requirement. As a result, the system hangs following the first bus access after reset. Fix Plan: HIP8 Version of MSC8102, which is the MSC8122 device Workaround: Use only a compliant external arbiter or the internal MSC8102 arbiter. System Number: 6998	1K94M
QSE32	Error in Parity Operation when BRx[30]:DR = 1 Date Added: 6/2002 Description: When data pipeline mode is chosen and port size is less than 64bit, parity check will fail for read access of size bigger than the port size, on the second data beat (psdval). Fix Plan: HIP8 Version of MSC8102, which is the MSC8122 device Workaround: Use BRx[30]:DR = 0. System Number: 7570	1K94M

Silicon Errata

Errata Number	Errata Description	Mask
QSE34	Bus Busy Disable Mode Can Hang 60x Bus in Multi-Master Systems Date Added: 6/2002 Description: The bus busy disable mode (SIUMCR[0]:BBD = 1) cannot be used if the MSC8102 is not the only master on the 60x system bus. Using this mode in such a system can cause the 60x bus to hang. Fix Plan: HIP8 Version of MSC8102, which is the MSC8122 device Workaround: 1. If the external master supports the $\overline{ABB}$ signal, do not use the bus busy disable mode and connect this signal to the MSC8102. The $\overline{DBB}$ signal can either be connected or can be pulled up. 2. If the external master does not support the $\overline{ABB}$ signal, do one of the following: a. Do not use the bus busy disable mode and generate the $\overline{ABB}$ signal externally. The $\overline{DBB}$ signal can either be connected or can be pulled up. The following external $\overline{ABB}$ implementation should be sufficient to work around the problem: Assert the $\overline{ABB}$ signal whenever a qualified bus grant for the external master is sampled (Bus grant asserted while $\overline{ARTRY}$ and $\overline{ABB}$ are negated). Negate the $\overline{ABB}$ signal when there is no qualified bus grant. The negation of $\overline{ABB}$ should be as follows: Drive $\overline{ABB}$ to VDD for half a clock cycle and then stop driving it (HIGH-Z). b. If the internal arbiter and up to two external masters are used, connect the external bus grants (through an AND gate if more than one) to an available external bus request and define the priority for that request to be the highest in the PPC_ALRH register. The $\overline{DBB}$ signal can either be connected or can be pulled up.	1K94M
QSE37	Broadcast failure After Burst (64bit/sync mode) Description: When a broadcast is performed before previous write burst data propagates to its target, it may cause an overflow of the write FIFO with no error indication in the DSI status bit of the DSI Error Register (DER). Fix Plan: HIP8 Version of MSC8102, which is the MSC8122 device Workaround: Do not perform a broadcast as the next access after a write burst. Perform another type of access in between. System Number: 7839	1K94M
QSE39	Bus Monitor Stuck Pending for PSDVAL. Description: When an external slave that does not use PSDVAL is accessed, if it returns $\overline{TA}$ on the same cycle that $\overline{TS}$ is asserted, then the bus monitor may be stuck, causing $\overline{TEA}$ after timeout. Fix Plan: HIP8 Version of MSC8102, which is the MSC8122 device Workaround: Disable the bus monitor (SYPCR[PBME]=0 in systems that have external slaves without PSDVAL or define a pipeline depth 1 (BCR[PLDP]=1) to avoid concurrent $\overline{TA}$ and $\overline{TS}$ System Number: 3759	1K94M
QSE40	Device Withstands ESD CDM Stress of 400V Instead of 500V Device Withstands ESD MM Stress of 185V Instead of 200V Date Added: 3/31/2004 Description: Device meets the ESD specifications for Human Body Model (HBM) of 1000V, but devices does not withstand Machine Model (MM) of 200V, and it does not withstand the Charged Device Model (CDM) of 500V. Workaround: N/A System Number:	1K94M

How to Reach Us:

Home Page:

www.freescale.com

E-mail:

support@freescale.com

USA/Europe or Locations not listed:

Freescale Semiconductor
Technical Information Center, CH370
1300 N. Alma School Road
Chandler, Arizona 85224
+1-800-521-6274 or +1-480-768-2130
support@freescale.com

Europe, Middle East, and Africa:

Freescale Halbleiter Deutschland GMBH
Technical Information Center
Schatzbogen 7
81829 München, Germany
+44 1296 380 456 (English)
+46 8 52200080 (English)
+49 89 92103 559 (German)
+33 1 69 35 48 48 (French)
support@freescale.com

Japan:

Freescale Semiconductor Japan Ltd.
Headquarters
ARCO Tower 15F
1-8-1, Shimo-Meguro, Meguro-ku,
Tokyo 153-0064, Japan
0120 191014 or +81 3 5437 9125
support.japan@freescale.com

Asia/Pacific:

Freescale Semiconductor Hong Kong Ltd.
Technical Information Center
2 Dai King Street
Tai Po Industrial Estate
Tai Po, N.T. Hong Kong
+800 2666 8080

For Literature Requests Only:

Freescale Semiconductor Literature Distribution Center
P.O. Box 5405
Denver, Colorado 80217
1-800-441-2447 or 303-675-2140
Fax: 303-675-2150
LDCForFreescaleSemiconductor@hibbertgroup.com

Information in this document is provided solely to enable system and software implementers to use Freescale Semiconductor products. There are no express or implied copyright licenses granted hereunder to design or fabricate any integrated circuits or integrated circuits based on the information in this document.

Freescale Semiconductor reserves the right to make changes without further notice to any products herein. Freescale Semiconductor makes no warranty, representation or guarantee regarding the suitability of its products for any particular purpose, nor does Freescale Semiconductor assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters which may be provided in Freescale Semiconductor data sheets and/or specifications can and do vary in different applications and actual performance may vary over time. All operating parameters, including "Typicals" must be validated for each customer application by customer's technical experts. Freescale Semiconductor does not convey any license under its patent rights nor the rights of others. Freescale Semiconductor products are not designed, intended, or authorized for use as components in systems intended for surgical implant into the body, or other applications intended to support or sustain life, or for any other application in which the failure of the Freescale Semiconductor product could create a situation where personal injury or death may occur. Should Buyer purchase or use Freescale Semiconductor products for any such unintended or unauthorized application, Buyer shall indemnify and hold Freescale Semiconductor and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, directly or indirectly, any claim of personal injury or death associated with such unintended or unauthorized use, even if such claim alleges that Freescale Semiconductor was negligent regarding the design or manufacture of the part.

Freescale™ and the Freescale logo are trademarks of Freescale Semiconductor, Inc. StarCore is a trademark of StarCore LLC. All other product or service names are the property of their respective owners.

© Freescale Semiconductor, Inc. 2003, 2005.