
Release Notes

Freescale eTPU(2) Development Suite v10.0 Release Notes for Patch 1.1

TABLE OF CONTENTS

1	<i>Known issues and Workarounds</i>	1
2	<i>Changes included in Patch 1.1</i>	1
2.1	<i>Simulator changes</i>	1
2.2	<i>Compiler changes</i>	2

1 Known issues and Workarounds

Issue ID	Description
MTWX46525	<p>Issue: Switch between multiple projects in the same workspace might result in unpredictable behavior.</p> <p>Workaround: Debug one project at a time</p>
MTWX46628	<p>Issue: Trace information file is generated in D:\</p> <p>Workaround: Make sure that the workspace directory is on the same drive as the installation directory.</p>

2 Changes included in Patch 1.1

2.1 Simulator changes

- Fix for MTWX47440: The capture registers source in some conditions was different that the one specified by the TBS[1] flag
- Fix for MTWX47720: Microcode changes to TBS flags don't update TBS register value



- Fix for MTWX47974: In em_b_dt mode, MatchB is unblocked by the clearing of MRLA

2.2 Compiler changes

- Upgraded to 1.4.3 version, see ETPU_10\Release_Notes\Compiler_Notes\FET Release Notes.txt for details