

0000-000-43011 SOLDERPASTE_1 COMP SIDE 2A0




0000-000-43011

SILKSCREEN_1


COMP

SIDE

2A000




0000-000-43011 SOLDERMASK_1 COMP SIDE 2A00



0000-000-43011

SIGNAL_1


COMP SIDE 2A1



0000-000-43011

SIGNAL_2

SOLDER SIDE 2A2




0000-000-43011

SOLDERMASK_2


SOLDER

SIDE

2B00



0000-000-43011 SILKSCREEN_2 SOLDER SIDE 2B000




0000-000-43011

SOLDERPASTE_2

SOLDER

SIDE


2B0



0000-000-43011
DRILL DRAWING

DRILL CHART: TOP to BOTTOM			
ALL UNITS ARE IN MILLIMETERS			
FIGURE	SIZE	PLATED	QTY
E	0.2000	PLATED	35
G	0.3000	PLATED	44
J	0.4000	PLATED	12
L	0.5000	PLATED	4
⊙	0.7000	PLATED	4
Ⓢ	0.8000	PLATED	22
Ⓤ	0.9000	PLATED	2
Ⓐ	1.0000	PLATED	17
Ⓟ	0.6500	NON-PLATED	1
Ⓛ	1.1000x0.5000	PLATED	4
Ⓟ	0.9500x0.6500	NON-PLATED	1

TOTAL HOLES: 146



PANEL DRAWING