


LPC546xx-540xx Eval brd 3.3V LCD assembly



2nd Operation LCD assembly steps.

- 1) With LCD screen facing towards pcb, insert 40 pin FFC and 6 pin FFC into respective J16 and J17 connectors.
- 2) place 2-side tape near each identified "tape" box. Ensure the tape is placed so it does not stick to the FFC but only to the metal case of LCD.
- 3) Fold back the LCD, pressing down to compress the EMI fingers (M1 - M4) and secure to 2-sided tape.

position tape to be between the two FFC cables.