NXP LPC84x Example Code Bundle Release Notes

Example Code Bundle LPC84x version release history and known issues

Example Code Bundle LPC84x Release Notes

The version history and known issue lists on this page are for v1.xx releases of Example Code Bundle only.



Example Code Bundle v1.2 release (Released: 12/19/2017): NXP LPC84x

Features Added

None

Changes and Fixes

• Corrected the FAIM_and_Clocks.c source to include correct implementation of the FAIM bit usage

Known issues

None

Example Code Bundle v1.1 release (Released: 11/14/2017): NXP LPC84x

Features Added

Add capacitive touch examples

Changes and Fixes

• Corrected system.c to put the GPIO pins into inactive mode when using external crystal

Known issues

• None

Example Code Bundle v1.0 release (Released: 06/14/2017): NXP LPC84x

Features Added

None

Changes and Fixes

None

Known issues

None

How to Reach Us

Home Page: www.nxp.com

Web Support: www.nxp.com/support

USA/Europe or Locations Not Listed:

NXP Semiconductor

Technical Information Center, EL516

2100 East Elliot Road

Tempe, Arizona 85284

+1-800-521-6274 or +1-480-768-2130

www.nxp.com/support

Europe, Middle East, and Africa:

NXPHalbleiter Deutschland GmbH

Technical Information Center

Schatzbogen 7

81829 Muenchen, Germany

+44 1296 380 456 (English)

+46 8 52200080 (English)

+49 89 92103 559 (German)

+33 1 69 35 48 48 (French)

www.nxp.com/support

Japan:

NXP Semiconductor

ARCO Tower 15F

1-8-1, Shimo-Meguro, Meguro-ku,

Tokyo 153-0064, Japan

0120 191014 or +81 3 5437 9125

support.japan@nxp.com

Asia/Pacific:

NXP Semiconductor Hong Kong Ltd.

Technical Information Center

2 Dai King Street

Tai Po Industrial Estate

Tai Po, N.T., Hong Kong

+800 2666 8080

support.asia@nxp.com