

Certification date: Expiry date: Certificate number: IATF Certificate number: 10 May 2021 9 May 2024 10430841 0398565

LRQA

LRQA

1004

L DOA

LRQ/

LRQ/

LDO

LPQA

LRQ/

LRQ/

LRQA

LRQA

LRQA

LRQ/\

LRQ/

LRQ/

LRQ/

LRQ/

LRQA

Certificate of Approval

This is to certify that the Management System of:

NXP USA, Inc.

No. 10, Jing 5th Rd., Nanzi Dist., R.O.C., Kaohsiung City 81170, Taiwan

has been approved by LRQA to the following standards:

IATF 16949:2016

Approval number(s): IATF 16949 - 0078056

This certificate is valid only in association with the certificate schedule bearing the same number on which the locations applicable to this approval are listed.

The scope of this approval is applicable to:

Design and Manufacture of Semiconductors.

Ciffef Mukley

Cliff Muckleroy

Area Operations Manager Americas

Issued by: LRQA Limited





Location **Activities** NXP (China) Management Ltd. IATF 16949:2016 After Sales. 1F-3F, No. 10 Building, No. 22 Jinyu Avenue, Liangjing New District, Chongqing 401120, China NXP Semiconductors Taiwan Ltd. IATF 16949:2016 Customer Service, Logistics. 9F & 10F, No. 19-5, San Chong Road, Nan Gang District, Taipei 11501, Taiwan IATF 16949:2016 **NXP Semiconductors Taiwan Ltd** Sales, After Sales. 6F-6, 7F, No. 66, San Chong Road, Nan Gang District, Taipei 11501, Taiwan **NXP Semiconductors Taiwan Ltd** IATF 16949:2016 Sales, After Sales; Supplier Management. 4F East, No. 19-8, Sanchong Road, Nan Gang District, Taipei 11501, Taiwan **NXP Semiconductors Austria GmbH** IATF 16949:2016 Product Design; Aftersales; Human Resource; Marketing. Mikron-Weg 1, A-8101, 8101 Gratkorn, Steiermark, Austria IATF 16949:2016 **NXP Canada Inc** Product Design. 1 Hines Road, Kanata, Hines Road, Kanata, ON K2K 3C7, Ontario, Canada NXP (China) Management Ltd. IATF 16949:2016 Sales, After Sales. Shanghai (BMIC) - Puxi, 19F, 20F and 21F BM InterContinental Business Center, 100 Yu Tong Rd., Shanghai 200070, China NXP (China) Management Ltd IATF 16949:2016 Product Design, HR. No. 192 Liangjing Road, Pudong New Area, Shanghai City 201203, China NXP Qiangxin (Tianjin) IC Design Co., Ltd IATF 16949:2016 Product Design. A1, 3rd floor Tianda, High-tech Park No.80 4th Street, TEDA, Tianjin 300457, China



Revision/Re-issue date: 7 February 2022

NXP (China) Management Ltd.

Jiangsu Province 215011, China

LRQA Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'LRQA'. LRQA assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant LRQA entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

Product Design.

Issued by: LRQA Limited, 1 Trinity Park, Bickenhill Lane, Birmingham B37 7ES, United Kingdom

No. 288, Zhuyuan Road, Suzhou New District, Suzhou City,

LRQA

LRQA

LRQA

LRQA

LRQ/

LRQ/

LRQ/

S. New Street, and

LPO/

LRQA

LRQA

LRQ/

LRQA

LRQ/

LRQ/

LRQA


LRQ/

LRQ/



Location	Activities
NXP Semiconductors (Tianjin) Ltd No. 15 Xinghua Avenue, Xiquing Economic Development Area, Tianjin 300385, China	IATF 16949:2016 Product Design.
NXP Semiconductors (Tianjin) Ltd No. 9, Weiwu Road, Micro-electronics Industrial Park, XiQing Dist, Tianjin, China 300385, China	IATF 16949:2016 Testing.
NXP (China) Management Ltd. Exchange Building 23rd Floor, No. 118 Jianguo Road, Chaoyang District, Beijing 100022, China	IATF 16949:2016 Product Design.
NXP Semiconductors Czech Republic s.r.o. 1.máje 1009, 756 61 Rožnov pod Radhoštěm, Czech Republic	IATF 16949:2016 Product Design, Customer Service, Human Resources.
NXP Semiconductors Czech Republic s.r.o. Sochorova 3232, Brno-Žabovřesky, 616 00 Brno, Czech Republic	IATF 16949:2016 Product Design.
NXP Semiconducteurs France S.A.S. 134 Avenue du General Eisenhower, B.P. 72329, 31023 Toulouse, France	IATF 16949:2016 Product Design.
NXP Semiconductors Germany GmbH Prager Strasse 2a, 01069 Dresden, Germany	IATF 16949:2016 Product Design.
NXP Semiconductors Germany GmbH Schatzbogen 7, 81829 Munich, Germany	IATF 16949:2016 Product Design; Aftersales; Sales; Marketing.
NXP Semiconductors Germany GmbH Troplowitzstrasse 20, 22529 Hamburg, Germany	IATF 16949:2016 Product Design; Aftersales; Human Resource; Marketing; Contract Review.
NXP Semiconductors Hungary Ltd. Budafoki Ut 91-93, 1117 Budapest, Hungary	IATF 16949:2016 After Sales.





LRQA Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'LRQA'. LRQA assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant LRQA entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

Issued by: LRQA Limited, 1 Trinity Park, Bickenhill Lane, Birmingham B37 7ES, United Kingdom

LRQA

LRQ/



Location	Activities
NXP India Pvt Ltd Plot No. 2 & 3 & 18, Sector 16A, Noida, 201301, Uttar Pradesh, India	IATF 16949:2016 Product Design.
NXP India Pvt Ltd 1st Floor, Block-3, DLF Cyber City, Plot No. 129 to 132, APHB Colony, Gachibowli, 500019, Hyderabad, India	IATF 16949:2016 Product Design.
NXP India Pvt. Ltd. Mfar-Manyata Tech Park Greenheart-Phase III, Nagawara, Bangalore, 560 045, India	IATF 16949:2016 Product Design.
NXP Japan Ltd Yebisu Garden Place Tower 24F, 4-20-3 Ebisu, Shibuya-ku, Tokyo 150-6024, Japan	IATF 16949:2016 Sales, After Sales, Marketing.
NXP Semiconductors Mexico S de RL de CV Periferico Sur # 8110, Col. El Mante, 45609 Tlaquepaque, Mexico	IATF 16949:2016 Product Design, After Sales.
NXP Semiconductors Netherlands BV Elekronicaweg 40, 2628 Delft, The Netherlands	IATF 16949:2016 Product Design.
NXP Semiconductors Netherlands B.V. High Tech Campus, 5656 Eindhoven, The Netherlands	IATF 16949:2016 Product Design; Information Technology.
NXP Semiconductors Netherlands B.V. Gerstweg 2, 6534 AE Nijmegen, The Netherlands	IATF 16949:2016 Product Design.
NXP Semiconductors Moscow LLC 4 Savelkinsky Proezd Zelenograd, Moscow, 124482, Russian Federation	IATF 16949:2016 Product Design.
NXP Semiconductors Singapore Pte Ltd 1 Fusionopolis Walk, #02-11, North Tower, Solaris, Singapore 138628, Singapore	IATF 16949:2016 Sales, Marketing, Purchasing, After Sales, Supplier Management, Process Design.



Revision/Re-issue date: 7 February 2022

LRQA Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'LRQA'. LRQA assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant LRQA entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

Issued by: LRQA Limited, 1 Trinity Park, Bickenhill Lane, Birmingham B37 7ES, United Kingdom

LRQA

LRQ/

LRQA



Location	Activities
NXP Semiconductors Nordic AB Kronborgsgrand 19, SE-164 46 Kista, Sweden	IATF 16949:2016 Product Design.
NXP Laboratories UK Ltd Pegasus House, 3 Bramah Avenue Scottish Enterprise Technology Park, East Kilbride, Glasgow, Scotland, G75 0RD, United Kingdom	IATF 16949:2016 Product Design, Human Resources, and After Sales.
NXP Laboratories UK Ltd The Cattle Barn, Upper Ashfield Farm, Hoe Lane, Romsey, Southampton, S051 9NJ, United Kingdom	IATF 16949:2016 Product Design.
NXP USA, Inc 6501 William Cannon Drive West, Austin, TX, 78735, United States	IATF 16949:2016 Product Design and Quality Headquarters.
NXP USA, Inc 1300 North Alma School Road, Chandler, AZ, 85224, United States	IATF 16949:2016 Product Design.
NXP USA, Inc. 3501 Ed Bluestein Boulevard, Austin, TX, 78736, United States	IATF 16949:2016 Product Design.
NXP Semiconductors Romania SRL Campus 6, Bulevardul Iuliu Maniu 6L București, Romania	IATF 16949:2016 Product Design, Customer Service, Human Resource, Information Technology.
NXP Malaysia Sdn Bhd. Jalan SS 8/2, Sungai Way, Free Trade Zone, Petaling Jaya, 47300 Kuala Lumpur, Malaysia	IATF 16949:2016 Product Design.
NXP Manufacturing (Thailand) Ltd 303 Moo 3 Chaengwattana Road, 10210, Bangkok, Thailand	IATF 16949:2016 Product Design.



Revision/Re-issue date: 7 February 2022

LRQA Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'LRQA'. LRQA assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant LRQA entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

Issued by: LRQA Limited, 1 Trinity Park, Bickenhill Lane, Birmingham B37 7ES, United Kingdom

LRQA

LRQ/